11798

5/102-

Diag. Cht. No. 5802.

Form 504

U. S. DEPARTMENT OF COMMERCE
COAST AND GEODETIC SURVEY

DESCRIPTIVE REPORT

Type of Survey Shoreline
Field No. Office No. T-11798
LOCALITY
State Oregon
General locality Coos Bay
Locality North Bend - Glasgow Pt.
1965-67
CHIEF OF PARTY V.R. Sobieralski Div. of Photogrammetry, Wash., D.C.
LIBRARY & ARCHIVES
DATE Sept. 20, 1967

сомм-ос 61300

	DESCRIPTIVE R	EPORT - DAT 7-11798	A RECORD	
ROJECT NO. (11):	- , - , 			
Рн-6608				
ELD OFFICE (II):		· <u>·</u> ·	CHIEF OF PARTY	
Seattle, Wash.	(Portland, Oregon))	H.J. Seaborg	
OTOGRAMMETRIC OFFICE			OFFICER-IN-CHARGE	
Washington, D.C	•		J.E. Waugh	
Field: July 30 Field, Suppleme Office: March Field Edit: Oc), 1965 nt 1: Nov. 2, 196 22, 1966	65		
thod of compilation (ii B-8 Stereoplott				
NUSCRIPT SCALE (III):		STEREOSC	OPIC PLOTTING INSTRUM	ENT SCALE (III):
TE RECEIVED IN WASHING	TON OFFICE (IV):	DATE REP	ORTED TO NAUTICAL CH	ART BRANCH (IV):
PPLIED TO CHART NO.		DATE:	DAT	E REGISTERED (IV):
OGRAPHIC DATUM (III):			VERTICAL DATUM (III)	:
N.A. 1927			MEAN SEA LEVEL EXC	EPT AS FOLLOWS:) refer to mean high water
2,21	·		Elevations shown as (5)	_
			i.e., mean low water or n	
FERENCE STATION (III):			<u>'</u>	
VT.:	LONG.:		ADJUSTED	<u></u>
ANE COORDINATES (IV):			STATE	ZONE
•	X =			
R (IV) WASHINGTON OFFICE	WHETHER THE ITEM IS TO BE EN			

DESCRIPTIVE REPORT - DATA RECORD

FIELD INSPECTION BY (II):		DATE:
J.C. Lajoye		Aug. 1965
MEAN HIGH WATER LOCATION (III) (STATE DA Office interpretation fi by field edit revision.	rom tide-controlled photography	, supplemented
PROJECTION AND GRIDS RULED BY (IV):		DATE 7-19-66
A.E. Roundtree		1419-00
PROJECTION AND GRIDS CHECKED BY (IV): R. Glaser		7-21-66
CONTROL PLOTTED BY (III):		DATE
D. Barton H. Lucas		7-22-66
CONTROL CHECKED BY (III):		DATE
R. A. Youngblood		7-23-66
RADIAL PLOT OR STEREOSCOPIC CONTROL	EXTENSION BY (III):	DATE
G.M. Ball		July 1966
STEREOSCOPIC INSTRUMENT COMPILATION (III): PLANIMETRY	DATE
R.A. Youngblood	x	July-Sept 1966
	CONTOURS	DATE
MANUSCRIPT DELINEATED BY (III):		DATE
R.A. Youngblood		July-Sept 1966
None - See the Compilati	ion Report	DATE
PHOTOGRAMMETRIC OFFICE REVIEW BY (III) J. Battley	:	May 1967
REMARKS:		

DESCRIPTIVE REPORT - DATA RECORD

CAMERA (KIND OR SOURCE) (III):

	· · · · · · · · · · · · · · · · · · ·	PHO:	TOGRAPHS (III)				
NUMBER	DATE		TIME	SCALE	5	AGE OF TH	
65 L(C) 6145 -		1965	1534-1541	1:15,000		elow M	
6174 65 L(C) 6175 -	11		1545-1551	Ħ	1.31 b	elow M	W H
6197 65 L(c) 6200 - 6225	ñ		1601-1608	11	1.7 b	elow M	HW
	~~.						
			TIDE (III)		<u> </u>		_
					RATIO OF RANGES	MEAN RANGE	SPRING RANGE
REFERENCE STATION: Cresc	ent City					5.1	6.9
BORDINATE STATION: COOB	Bay					5.2	7.0
SUBORDINATE STATION:			· · · · · · · · · · · · · · · · · · ·				
WASHINGTON OFFICE REVIEW BY	(IV): J. B	attle	у У		DATE: May	1967	1
PROOF EDIT BY (IV):					DATE:		
NUMBER OF TRIANGULATION STA	TIONS SEARCH	ED FOR	11):	RECOVERED:	IDENTIFIE	D:	
NUMBER OF BM(S) SEARCHED FO	R (II):			RECOVERED:	IDENTIFIE	D	
NUMBER OF RECOVERABLE PHOT	TO STATIONS ES	STABLISH	IED (III):	 	1		
NUMBER OF TEMPORARY PHOTO	HYDRO STATIO	NS ESTA	BLISHED (III):				

SUMMARY TO ACCOMPANY DESCRIPTIVE REPORT Job PH-6608

May 1967

This project is comprised of three maps, T-11798 thru T-11800, covering Coos Bay, Oregon, in its entirety. It is the second in a series of harbor line survey projects to be done for the Portland District, Corps of Engineers. In addition, these surveys will provide complete topography of of the shoreline area for the Marine Chart Division.

The manuscripts were compiled at a scale of 1:5,000 using 1:15,000 scale color photography taken in August 1965.

Analytic aerotriangulation methods were used to bridge the three strips of color photography covering the project area.

Field operations encompassed the recovery and identification of horizontal control for bridging, the establishment and location of harbor line reference monuments, and the investigation of landmarks and aids.

Field edit was accomplished for each manuscript in liaison with the Corps of Engineers. The recommendations made by the Corps of Engineers were included in the field edit report.

Compilation was completed in the Washington office and final copies delivered to the Portland Office, Corpstof Engineers in May 1967. Two cronaflex copies and three ozalids of each sheet were supplied.


A copy of these surveys will be registered in the Bureau Archives under their respective T-numbers.

<u>د</u> و

Submitted by:

Jeter P. Battley, Ir.

Jeter P. Battley, Jr.



FIELD INSPECTION REPORT JOB PH-6608

2. AREAL FIELD INSPECTION

No field inspection was done in this area.

3. HORIZONTAL CONTROL

The horizontal control phase of this job was planned as a reimbur-sable project with the U. S. Engineers Office in Portland for the purpose of locating control points adjacent to points along the Harbor Line in the Coos Bay Harbor area.

Reconnaissance for this phase was done in the fall of 1964 and the proposed traverse was forwarded to the Washington Office for approval.

Instructions for the reimbursable portion of this project were issued July 30, 1965. Instructions for the Photogrammetric phase of the job were issued November 11, 1965.

Field work was started in August, 1965, and continued until
September 12 when the unit was transferred to Job PH-6606. Work
was resumed on October 4 and continued until the completion of both
phases of the job on November 22. Completion of smooth work was done
in the Pacific Marine Center in Seattle.

In accordance with the letter from the Acting Chief, Geodesy Division, to the Portland Field Officer dated June 15, 1965, additional recommended lines were investigated. The only line found to be feasible was the traverse connection from HAYBARN (USE 1907) 1945 to ROGERS (USGS 1942) 1945 and the observation of the line MARSHFIELD HILL 1889 - ROGERS (USGS 1942) 1945. Other lines requested were either

blocked or could not be measured due to excessive vertical angle.

All lines shown along the traverse portion of the reconnaissance sketch were measured with the Geodimeter with the exception of the line HAYBARN (USE 1907) 1945 to HLT - 2 and the line BM D 249 (OSHD) to HLT - 25. These were taped in accordance with Photogrammetry Instructions 47.

The Geodimeter lines between HLT-21 and HLT-22 and between HLT-23 and HLT-24 are shorter than the minumum specified by the Job Instructions but these lines could not be taped as they are across water.

The line HLT-25 to HLT-26 was measured by Geodimeter but when the observing party attempted to turn the angles, the line was blocked by recently stacked logs. Consequently, the line HLT-27 to HLT-26 was measured by Geodimeter to provide a double determination of HLT-26.

All stations set were standard U. S. Engineers disks with the exception of HLT-\$4 (temp.). It was intended to mark this point as a permanent point on the traverse line but permission could not be secured from the Southern Pacific.

All distances measured by Geodimeter or taped were reduced to the horizontal as specified by the Job Instructions, and shown on "Traverse lengths reduced to Horizontal" a two-page list included with the data for the job. Computations for the reduction are also included.

Azimuth computations were made through the various lines and the

resulting error was distributed so as to supply the adjusted azimuth required by the instructions.

Wye levels were run through all Harbor Line Traverse points with ties to various bench marks in the area. Double zenith distances were measured to points not on the level lines. These are recorded in the appropriate volumes and listed on "Abstract of elevations, Wye Level Vol. 2" and on 21 Form 29 (Abstract of Zenith distances).

All lines measured by Geodimeter were single measured except those which were used to establish temporary control for Photogrammetry and mentioned under Item (a) Angles were observed as specified in the instructions.

(a) Temporary stations PAR, FAY, SAP and ZIP were established by this party to supply control for Photogrammetry in areas where no previous control had been established. These points were established by double run Geodimeter lines and 4 D&R from MARSHFIELD HILL 1889 and NORTH BEND (USE 1907) 1945.

Within the Harbor Line Control framework of this project:

- 33 New stations were established by traverse methods
- 1 Temporary station was established by traverse
- 1 New reference mark for MARSHFIELD HILL 1889 was established
- 20 Aids to navigation were located by intersection
- 2 Landmarks were located by intersection
- (b) No datum adjustments were made by this party.

- (c) All control used or identified was either established by the Coast & Geodetic Survey or tied to Coast Survey control by this survey
- (d) Stations in all areas required for photogrammetric control were identified except in the area at MABRY 1862 where the photo control was required on two adjacent flights. This was satisfied by the identification of North Bend Radio Station KBBR, Mast and North Bend Range Front Passing Light. The area at PIERCE 2, 1945, which has been destroyed was satisfied by the establishing and identifying of SAP(temp). Other areas in which control was required and in which no triangulation was available were covered by the identification of temporary stations mentioned in Item (a).
- (e) All Coast & Geodetic Survey stations shown on the Project
 Diagram were searched for and reported on Form 526. BUNKER
 (USGS) (Bunker Hill Lookout Tower) 1942 was torn down in
 October, 1965, but was in place when the photographs were
 flown. It was identified.

4. VERTICAL CONTROL

Vertical control as such was not required in this project. The vertical control necessary for the reduction of Geodimeter slope distances to the horizontal was established by Wye leveling with a Zeiss Opton level and Philadelphia rod over traverse stations with ties to Coast & Geodetic Survey Bench Marks. The following bench marks were recovered and Form 685A is submitted:

4. VERTICAL CONTROL (cont'd.)

Line 73, Oregon

Q 468

23 (USGS)

D 249 (OSHD)

A 198 (OSHD)

C 468

P.T.S. 16 (USGS)

A 58

This data is recorded in Vol. 1 of 1 - "Wye Leveling, PH-6608, Coos Bay Harbor Line 1965".

â Additional leveling for the reduction of Geodimeter lines to the horizontal was by Double Zenith Distances as required by the project instructions and is recorded in Form 252 "PH-6608, Coos Bay Harbor Line, Oregon".

5. CONTOURS AND DRAINAGE

Not applicable.

6. WOODLAND COVER

Not applicable.

7. SHORELINE AND ALONGSHORE FEATURES

Not applicable.

8. OFFSHORE FEATURES

Not applicable.

9. LANDMARKS AND AIDS

- (a) Five of the landmarks shown on Chart 5984 are recommended for deletion. Five landmarks are recommended for retention and three new landmarks have been recommended for charting. These are listed on separate Form 567.
- (d) 20 aids to navigation (fixed) were located by intersection.

9. LANDMARKS AND AIDS

(d) (cont'd.)

Two of these had been located in 1945 but inspection of the structures revealed new piling and although the Light List, Pacific Coast 1964 states that these two ranges have not been rebuilt, it was deemed better to locate them again during this survey.

Three fixed aids were identified on the photographs for location by photogrammetric methods.

10. BOUNDARIES, MONUMENTS AND LINES

Not applicable.

11. OTHER CONTROL

Four temporary stations were established by Geodimeter Traverse for Photogrammetric Control as noted in Item 3.

12. OTHER INTERIOR FEATURES

Not applicable.

13. GEOGRAPHIC NAMES

Geographic names are the subject of a special report by L. L. Riggers.

14. SPECIAL REPORTS AND SUPPLEMENTAL DATA

1. Geographic Names Report, Coos Bay, Oregon, Job PH-6608, December, 1965.

Respectfull∳\submitted

Jahn C. Lajoye

Super. Surveying Tech.

PHOTOGRAMMETRIC PLOT REPORT Special Purpose Maps Job PH-6608 Coos Bay, Oregon July 1966

21. Area Covered

This report covers an area of Oregon in the upper portion of Coos Bay Harbor. This area is to be mapped on three T-sheets; T-11798, T-11799, and T-11800 at a scale of 1:5,000.

22. Method

Analytic aerotriangulation methods were used to bridge three strips of "L" color photography at a scale of 1:15,000. The attached sketch of strips bridged shows the placement of triangulation furnished and those that were used in the final strip adjustment. Closures to control and to tie points have been tabulated. State plane coordinates (Oregon, South Zone) have been furnished for all bridge points.

23. Adequacy of Control

Horizontal control identified for bridging was more than adequate. Although many of the points were elevated objects which usually are not well suited for measuring on the STK, our results were very satisfactory.

25. Photography

The color photography was adequate with regard to coverage, overlap, and image definition.

Respectfully submitted

Approved and Forwarded

£ 🧐

હ હ

H. P. Fachert, Acting Chief Aerotriangulation Section

CLOSURE TO TRIANGULATION AND TIE POINTS (* Control Used In Final Adjustment)

Strip #1

Rogers (USGS), 1942 SS A (-1.1 -0.06) SS B* (-0.1 +0.14)

North Bend Range Front Passing Light, 1965
(Light was difficult to see because of glare off the water)
(-4.7 +0.15)

Jarvis Upper Range 2 Front Light 31, 1965 (-1.9 -0.88)

North Bend Radio Station KBBR Mast, 1965 (+1.0 +0.59)

SS A HLT 2, 1965 (+0.8)+0.12) 1st Model +0.1 +0.02) 2nd Model SS A -0.88) SS B* (-0.3 HLT 11, 1965 SS A-(+0.1 +0.79 SS B* (+0.3 -0.66HLT 14, 1965 SS A* (-0.7 +0.11) (+0.7)SS B--0.04)

Ferndale Upper Range Front Light, 1965 (Point was Questionable) (+4.5 -1.34)

Isthmus Slough Light 43, 1965 (0.0 -0.36)

Coos Bay Marshfield Radio Station, 1945 (+0.6 -1.00)

Zip (Temp.), 1965 SS A (+0.7 +0.62) SS B* (+0.1 -0.03)

Strip # 2

Bunker Hill Lookout Tower (USGS), 1942

*(-0.2 +0.48) 1st Model

-(-0.5 +1.00) 2nd Model

Isthmus Slough Light 43, 1965 (-0.2 +0.62) 1st Model (+0.4 +0.76) 2nd Model


```
Coos Bay Lumber Co. Stack, 1945
                                   (+0.5
                                          -0.40)
Coos Bay Radio KYNG Mast, 1965
                                  ·(+1.0
Coos Bay Lumber Co. Tank, 1945
                                   (+0.5
(+1.1
                                          +1.31) 1st Model
                                          +0.36) 2nd Model
                                   (+0.9
(+0.7
                                          -0.35) 1st Model
-0.46) 2nd Model
HLT 24, 1965
                        SS *
Ferndale Upper Range Front Light, 1965
HLT 14, 1965
                        SS B
Coos Bay Marshfield Radio Station Mast, 1965
     (Mast was very tall and difficult to see on one plate)
                                  (+1.2 +1.69)
                                  (-0.8)
White Point 4, 1922
                                          +0.51)
HLT 11, 1965
                        SS B*
Marshfield Channel Range Front Light, 1965
SAP (TEMP.) 1965
                        SS A
                        SS B*
North Bend Range Front Passing Light, 1965
                                  (-0.8^{\circ} + 0.44)
HLT 2, 1965
                       SS A (Not Visible On This Flight)
                                  (+2.4 -0.15) 1st Model
                                  (+0.1 -0.09) 2nd Model
                        SS B
North Bend Radio Station Mast, KBBR, 1965
                                         -0.01) 1st Model
-0.09) 2nd Model
                                  (-0.2
                TIE POINTS - STRIP # 2 TO STRIP # 1
66801
                    (+1.0
                           +2.48)
68801
                                   1st Model
68801
                                   2nd Model
```

```
63801
                     (+2.2
                            +1.10)
63802
                     +1.3
                            +0.17)
                                   1st Model
63802
                     +1.0
                            +0.17)
                                   2nd Model
                     +1.3
                            -0.37)
61801
58801
                     +2.7
                            -1.51)
                                   1st Model
58801
                            -1.56)
                                   2nd Model
                     +2.5
                     +2.7
                            -1.36)
59801
                                   1st Model
                            -1.43)
59801
                     +3.4
                                   2nd Model
57801.
                     +1.1
                            -1.51)
57802
                     +1.1
                            -3.42)
                     -0.8
57803
                            -1.33)
               TIE POINTS STRIP #2 TO STRIP #3
83802
                     -1.3
                            -0.07)
                     +2.2
85801
                            +0.07
85802
                     +3.5
                            +0.51)
                            -3.34)
87801
                     +0.2
                            -1.97
-1.35
87802
                     +0.2
89801
                     +1.0
89802
                    (+1.3
               STRIP #3
PAR (TEMP.), 1965
                                          -0.18)
                        SS A*
                                   (-0.6)
                        SS B.
                                   (-0.7)
                                          +1.42)
FAY (TEMP.), 1965
                        SS A
                                  (+5.4)
                                          -2.59)
        (Point was very Questionable)
                        SS B*
                                  (-0.9
                                          +0.31)
MARY (TEMP.), 1965
                                  (+1.5
(-1.0
                        SS A
                                          -0.14)
                        SS B*
                                          -0.26)
LOGGIE 1889 RM#1.
                        SS A*
                                   (+1.2
                                          -0.60
```

SS B-

(+0.5

+0.12)



TRIANGULATION STATIONS

- 1 NORTH BEND RADIO STA. KBBR MAST, 1965
- 2 JARVIS UPPER RANGE 2 FRONT LIGHT 31, 1965
- 3 NORTH BEND RANGE FRONT PASSING LIGHT, 1965 4 HLT 2, 1965 5 HLT 6, 1965 6 FERNDALE LOWER RANGE FRONT LIGHT, 1965

- 7 HLT 11, 1965 8 COOS BAY RADIO STA. KOOS, 1945
- 9 HLT 14, 1965
- 10 ISTHMUS SLOUGH LIGHT 43, 1965
- 11 FERNDALE UPPER RANGE FRONT LIGHT, 1965
- 12 BUNKER HILL LOOKOUT TOWER (USGS), 1942
- 13 ZIP (TEMP.), 1965
- 14 COOS BAY LUMBER COMPANY TANK, 1945 COOS BAY LUMBER COMPANY STACK, 1945
- 15 HLT 24, 1965
- 16 COOS BAY RADIO KYNG MAST, 1965

- 17 WHITE POINT 4, 1922 18 SAP (TEMP.), 1965 19 PAR (TEMP.), 1965 20 FAY (TEMP.), 1965
- 21 MARSHFIELD CHANNEL RANGE FRONT LIGHT, 1965

- 22 MARY, 1948 23 LOGGIE, 1889 24 ROGERS (USGS), 1942

COMPILATION REPORT Job PH-6608 Coos Bay Harbor, Oregon October 1966

31. Delineation

Three shoreline maps (T-11798 thru T-11800) at a scale of 1:5,000 were compiled to furnish a base for the Corps of Engineers for the location of harbor lines and to provide planimetry in the shoreline area, including the location of landmarks and aids, for Marine Chart Division

The entire project was compiled on the B-8 stereoplotter using August 1965 color glass plates at 1:15,000 scale.

The interior limits of compilation were marked with a grease pencil on a set of color prints. These were compiled to include the first road parallel to the shoreline or its equivalent depending upon circumstances. Hard surface roads and streets were compiled in double lines to scale and dirt roads were shown by a double dashed line of uniform width. Large buildings along the waterfront, railroads, piers and all offshore structures were accurately located and delineated to scale.

Due to the extensive amount of floating lumber and log booms and the muddy character of the water, it was impossible to delineate the numerous channels existing in this area.

During compilation, these manuscripts were smooth drafted, eliminating the scribing process.

32. Control

Bridging furnished by aerotriangulation was sufficient to adequately compile the manuscripts.

33. Supplemental Data

Two Oregon State Highway Department maps, dated April 1965, were used for street names and highway numbers.

34. Contours and Drainage

Not applicable

÷ .

35. Shoreline and Alongshore Details

See Item 31.

35. Shoreline and Alongshore Details, cont.

The vertical datum for the shoreline on the manuscripts were MHW. The shoreline was compiled from color photographs taken August 26, 1965, between the hours of 15:38 and 16:04 Pacific Saving Time. At the time of photography the tide stage was about one foot to one and one half feet below MHW. The shoreline was delineated to the visible evidence on the photographs of the MHW line and the water level at the time of photography. On T-11799 the shoreline delineated on the marsh islands in Coos Bay is considered approximate as the islands were covered with logs and debris.

36. Offshore Details

See Items 31 and 35

37. Landmarks and Aids

Field investigation of landmarks and aids was made for use in marine charting and those recommended were shown on this project.

38. Control for Future Surveys

Inapplicable

39. Junctions

Each adjoining sheet overlapped by 15 seconds, resulting in accurate junctions between the surveys.

40. Horizontal and Vertical Accuracy

The manuscripts within the project comply with the National Standards of Accuracy.

41. thru 45.

Inapplicable

46. Comparison with Existing Maps

A comparison was made with planimetric maps T-8954, T-8955, T-8957 and T-8958, scale 1:10,000 dated 1949 and with USGS quad, Coos Bay, scale 1:62,5000 dated 1945.

47. Comparison with Nautical Charts

A comparison was made with Chart 5984, scale 1:20,000, 42nd edition, dated December 1964.

Submitted by:

R. A. Youngblood

Cartographic Technician

Approved by:

K. N. Maki

Chief, Compilation Section

Field Edit Report Project PH-6608

Harbor Line Surveys and Shoreline Mapping of Coos Bay, Oregon

Map Manuscripts T-11798, 11799, 11800 January, 1967

51. Methods The physical features of the discrepancy prints were visually checked in the field, utilizing a small skiff or vehicle. All of the office queries on the discrepancy prints were field checked and resolved. Field corrections, additions and annotations were made on the discrepancy prints in purple ink. The field inspection on the color photography is referenced to the discrepancy prints. Deletions were made in green ink.

The positions of three newly constructed dolphins, located on Sheet T-11798, were determined by sextant fix.

All aids to navigation and landmarks for charts were inspected and were found to be as mapped. One office identified, elevated water tank was field-verified as being of landmark value. It is listed on Form 567. Changes of the alongshore features were corrected on the discrepancy sheets.

In several instances the compilers were unable to interpret the mean high water line on the low, flat sand islands in Coos Bay. The mean high water line and the apparent mean high water line have been indicated on the color photography. Generally a definite line of demarcation is not apparent due to the gradual change in color tones. This area was inspected at high tide and, due to the flat gradient of the shore area, the field determination of the shoreline on the color photography is representative in these locations. Corrections and verification of shoreline features were made where shadows obscured the detail of the photo-images.

In the southeast section of Coos Bay, several tall stumps that had lodged in the shallow water areas were incorrectly compiled as dolphins. These features were deleted as the next spring flood waters of the Coos River will probably shift their location again. Several offshore areas that appeared as rock outcrops or obstructions were caused by drifting trees becoming lodged in the sand and other debris accumulating around them. They were considered to be of a temporary nature and were deleted.

Bluffs and hillsides in the Russell Point, Glasgow Point and Pierce Point areas were compiled and symbolized by the use of long hachures. Since most of the area in question is not strictly bluffs, but steep, wooded or brushy hillsides except where otherwise field noted on the discrepancy prints, the bluffs are not in evidence to the offshore observer.

An example on Sheet T-11798, in the vicinity of triangulation station MABRY, the station is on a steep wooded slope. A 20-25 foot vertical bluff extends upwards from the mean high waterline terminating at the foot of the wooded slopes. It is recommended in these areas where the bluffs are adjacent to the mean high water line they should be symbolized as short hachures, probably not more than 2 millimeters in length as indicated on the discrepancy prints. The area in back and above the bluffs should be considered as steep wooded slopes (unmapped).

All the horizontal control traverse stations with the "HLT" prefix were visited and the marks were found in place and recoverable except HLT-20(USE). This station had been destroyed by a bulldozer, but a new station HLT-20A(USE) was established at the same site. It is recommended, the horizontal control stations SIMPSON, 1862; TRAVERSE STATION 39+85.45 (USE), 1965; and HEAD, 1945, be added to the manuscripts. Several of the plotted horizontal control stations were deleted from the manuscripts. These stations were not recovered or have been destroyed and it is felt their plotted presence might lead future users of the maps to assume the stations were recoverable at the date of compilation. Pertinent information may be found for each station on their respective form 526, Recovery Note, Triangulation Station, which will accompany this report.

- 52. Adequacy of Compilation: In general the compilation appears to be accurate and complete, except in the cases of shadows obscured features and the ambiguous interpretation of certain photo-image.
- 53. Map Accuracy: The field testing of the manuscripts was not required.
- 54. Recommendations: The Corps of Engineers have requested the tabulation of the Oregon, South Zone, Lambert Plane Coordinates on their respective manuscripts as exemplified on the preliminary format copy. In the future the Corps of Engineers will probably furnish contractors and local engineers with copies of the maps and the quick reference to the coordinate positions would be advantageous. It is further recommended, the positions of all the plotted horizontal control stations including the intersection stations, except the fixed aids to navigation, should be included in the tabulation of positions. This could afford a ready access to the coordinate positions for azimuth determinations, etc., as desired by the local engineer.
- 55. Examination of Proof Copy: Arrangements were made with the Corps of Engineers to make preliminary examinations of the manuscript copies. Their reaction was considered to be favorable and a copy of their letter of approval including their recommendations will be submitted with this report.

56. Copies of the street maps of the cities of Coos Bay and North Bend, Oregon, were obtained by the field editor and Will be forwarded with this report.

Approved:

John O. Boyer, CDR, USESSA

perations Officer Pacific Marine Center Respectfully submitted,

Robert B. Melby

Supervisory Surveying Technician Pacific Marine Center

REVIEW REPORT T-11798 Shoreline Mapping May 1967

61. General Statement

See Summary in preface

62. Comparison with Registered Topographic Surveys

A comparison was made with surveys T-8954 and 8955, scale 1:10,000, dated 1949. These prior surveys are superseded by T-11798 for common details.

63. Comparison with Maps of Other Agencies

See Item 33 and 46 of the Compilation Report

64. Comparison with Contemporary Hydrographic Surveys

None

65. Comparison with Nautical Charts

A comparison was made with Chart 5984, scale 1:20,000, 42nd edition, dated December 1964. There are numerous changes, indicated by the three new surveys, in shoreline buildings and shoreline structures such as piers, piling and bulkheads. Coincident with the completion of this project, the Marine Chart Division was preparing to re-issue Chart 5984. A four-time reduction of each manuscript was ordered by the Marine Chart Division to revise these shoreline details, including landmarks and aids.

Approved by:

Reviewed by:

Chief, Photogrammetric Branch 100

Cartographer

Chief, Phytogrammetry Division Ach Ch

ஆChief, Marine Chart Division

U.S. DEPARTMENT OF CONNERCE Eric survey COAST AND GR

ITA ITLOATING AIDS ORXINGIDALITAISSMODHUIBERIS 🐍

STRIKE OUT 1WO

Coos cay, Oakcon

I recommend that the following objects thick and been inspected from convert to determine their value as landmarks to

DURING FIELD EDT charted on (_____ f___) the charts indicated.
The positions given have been checked after listing by R. A . Val. 16 32.000 THE POSITIONS OF ALL AIDS WERE VISUALLY INSPECTED

V. RALPH SOBIERALSKI

C (1) of 15 m	237	LOCATION ON STATE	· 	5 42.515 134013	44.734 124 13 02.028	30.365	3025 28.813 57.739 " " " " " " "	24.031	325 28.770 124 12 51.719 " " " " " " " "	24.827	3°23 33.372 46.324 " " " " " " " "	23 26.651	324 03.943 1240, 12 47.800 " " " " " "	12.779	22.739	3°22	• • • • • • • • • • • • • • • • • • • •
		CREGON		1284 4 432	Soco Banco C pass	33 / 1289 /	BEND LOWER RANGE	8200 RABGE FROMT LT 355 1291	Benn Range Reng 7	BEND 144095 (T. 38	12 NOSTH SEND UPPER RANGE FRONT LT 1294	BEND UPPER RANGE REAR LT. 1295 43	LE LOWER RANGE FROMT LT. 1298	LOWER RATION REAR LT.	UPPER RANGE FRONT LT 41 1298	UPPER RAHGE REAR LT. 1299 43°2	

This form shall be prepared in accordance with Hydrographic Manual, Publication 20.2, Sec. 1-55, 2-39, 6-36, 7-18 to 22 inclusive, and Fig. 79. Positions of chancel The date . heald be lendmarks and nontiouting alds to navigation, if redetermined, shall be reported on this form, Revisions shall show both the old and new positions. France for the chairs of the area and not by individual field survey sheets. Information under each column heading should be given.

Uscommind Madupat

U.S. DEPARTMENT OF COMMERCE

COAST AND GEODETIC SURVEY

Coos Bay Organa

7dos

I recommend that the following objects which Care need been inspected from courand to determine their value as landametes be charted on Contact Low the charts indicated. SIRKAR PERSENSE

STRIKE OUT TWO

NOCEDER STEERS TO BE CHARTED

: 4

C&GS FORM 567

SOBIER ALSK RACPH 2000 OF ALL AIDS WERE VISUALLY INSPECTED DURING The positions given have been checked after listing by A. A. Young BLOOD THE POSITIONS

CHARTS 5984 5984 = = Circl of TEAMS ERORENVO MANUE ERONISM ивроз спуш 11/18/62 LCCARON 1945 1965 11/13 1/12/17 1965 1 1965 ö = = TRIANG TRIANG Рното Prioro , 1 PHOTO 0.7 = = LIGULY 35.404 30.654 22.503 52,750 50.657 D.P. METERS 46.303 29.819 37,198 20.530 36.699 Lonerrace 124012 124010 124.09 124012 124012 124010 124,10 124013 10.092 124 10 POSITION 12490 ٥ 28.454 40.644 45.27 38.635 28.487 34.761 24,070 52.815 37.599 อ.ค.กะาสสอ LATITUDE® 43 022 43021 43021 4325 4325 4322 43022 43022 4302 43°21 0 -Tsleksi 1303 1288 1302 1305 1306 1308 1291 1307 1.304 1501 REAR LT ANORTH BEND RANGE FESHT PASSING LT. (Coo Bay Channey Lynt 25) MARSH FIELD CHANNEL RANGE FT. VI VINARSHFIELD RANGE REAR LT. MARSHELL CHANNEL RANGE CIGHT 28 SLOUGH LIGHT 43 COOS RIVER ENTRANCE LT ١, DESCRIPTION . H. Ch. COOS RIVER CHANNEL CATCHING SCOUGH LI Coos RIVER LT. しことととはい Istanius STATE OREGON CHARTING

Usconation leasting This form shall be prepared in accordance with Hydrographic Manual, Publication 20.2, Sec. 1-55, 2-39, 6-36, 7-18 to 22 inclusive, and Fig. 79. Positions of charted The data should be landmarks and nontine and to navigation, if redetermined, shall be reported on this form. Revisions shall show both the old and new positions. considered for the charts of the area and not by individual field survey sheets. Information under each column heading should be given. FACULATE STOOMES AND SHEERS

With the military of the there's COAST AND GRODING OUTARY

TO POST TO THE TOTAL TO THE TOT

STATES NOW SELECTION Coos Byy, Oneron

から

4

V. RALPH SOBIERLASKI

I recommend that the following objects which they show been inspected from seaward to determine their value as landmarks be cleared on (This first) the charts i leated. To The CHARTHED X

STRIKE OUT 1TO

COCS PARK CO

YOUNGBLOOD VISUALLY INSPIROTED The positions given have been checked after listing by R. A. Were arids 011 a

CHARTS AFFECTED Chief of Parin 5984 , '**=**orranour chang тялно песлам 11/18/65 12/67 1/12/67 1/12/67 Locardon 1112/67 1/12/67 LOSATION CZ LOSATION AND OUNVEY No. Triang Photo Photo TRIANG Рното Triang = DATAGE 35.250 46.923 D. P. P. TTERS 28.404 1147.4 04.344 03.661 41.624 50.961 LONCHUBER 124/3 124 12 124011 158.469 124012 POSITION 1101.61 124013 110621 . 481 32.389 15.562 54.180 48.114 D. H. RETURE 05.949 36.945 185.6 45.817 LATITUDES 4323 43023 43 22 43°21 ৢ৻৽ $\vec{\kappa}$ 4321 0 43 43 245) FT 160 FT (240) 160 FT (260) 240 FT. (141) 250 (168) 137 RADIO STATION KYNG MAST-1965 (Coos BAY (MARSHFIELD) RADIO STAT. KOOS STEEL TOWER (USGS 1942) 194 GOOS BAY, COOS HEAD TIMBER CO STK STACKY COUS Bay Lumber Co Stack 194 TANKER COOS BBY Lumber Co Tonk 194 Hr= 250 (260) 45=137 (147) The positions of During Figure DESCRIPTION STACK TANK Coos BAY OREGON RADIO MAST STACK TANK (E/ev) CHARTHUS NAME RADIO MAST BLATC STACK.

This form shall be prepared in accordance with Hydrographic Manual, Publication 20.2, Sec. 1-55, 2-39, 6-36, 7-18 to 22 inclusive, and Fig. 79. Positions of chatted Publications The data should be -P1211 landmarks and nontionting aids to navigation, if redetermined, shall be reported on this form. Revisions shall show both the old and new positions. considered for the charts of the area and not by individual field survey sheets. Information under each column heading should be given. CHADULATE SUCCHES AND METERS

USCOMM-DC 16234-PC1

Pase Ut

Compilation.

landmark Vatue-during

be of

7

appeared

Buk

This

1/12/67

Triang

1/12/17

Photo

15.216

12493

44.396

43.84

43,25

Radio Mast North Bend Radio Star KBBR 1945

Water Tank, woulden clevel

* TANKEIN

30.263

COURT FACE CONTRACTOR CONTRACTOR

THE ALTHARTS NOT OTHERS

recommend that the following objects which Ca 3 (Lays 1907) been inspected from seaward to determine their volue as lunium's to fo un touchar

Curify the deleted from the charts indicated.
The positions given have been checked after listing by

STRIKE SUT TWO

CAGS FORF CO

								Ë,	Child of Firsts
STATE		<u> </u>		РОЗІТІОМ		. Cersion		7274	
	ONEGON		CATITUDES	#EGNAMES #	1	LOGATION	DATA PO	2 2 2	C1::::13
CHARTING	Descalmtor:	DIGNAL	0 1 D.A.M.TERS	o / nerens	מעבעם	SURVEY No.	Locamon		10 11 12 12 12 12 12 12 12 12 12 12 12 12
STACK (EAST OF, THREE)	STATION DESTROYED (REBUILT)		43 23 1306.1	00.926 124 13 20.8	NA 1927	10.000	1945		5684
FLAG TOWER			2	5		=	=		=
CUPOLA (HOTEL)	(Not Outstanding)		22	7.2	=	=	=		Ę.
STACK *	Тови Оочи	7	25.194 43_21 808.4	12	11	E	=		<u> </u>
STACK	TORN DOWN	· ·	43 21 747.6	124 11 934.8	=	Ε	=		=
					Ý				
				1	-			1	
				200					ļ,
			1/1/	100 78					
			7 7	a pi					
#		V	A PORTO	1,00					
<i>*</i>		2							
,			1	T T					

This form shall be prepared in accordance with Hydrographic Manual, Publication 20.2, Sec. 1-55, 2-39, 6-36, 7-18 to 22 inclusive, and Fig. 79. Positions of chatted The data should be , landmarks and nontiouting aids to navigation, if redetermined, shall be reported on this form. Revisions shall show both the old and new positions. considered for the charts of the area and not by individual field survey sheets. Information under each column heading should be given.

* TABULATE SECORDS AND METERS

USCOMM-DC 16234-P61

GEOGRAPHIC NAMES

FINAL NAME SHEET

PH-6608 (Coos Bay, Oregon)

T-11798

Coos Bay

Glasgow

Glasgow Point

Kentuck Inlet

Kentuck Slough

North Bend

North Point

Russell Point

Willanch Creek

Willanch Inlet

Willanch Slough

Wraight

Approved by:

A. Joseph Wraight

Chief Geographer

Prepared by:

Frank W. Pickett Cartographic Technician

NAUTICAL CHART DIVISION

RECORD OF APPLICATION TO CHARTS

T-11798 FILE WITH DESCRIPTIVE REPORT OF SURVEY NO.

INSTRUCTIONS

A basic hydrographic or topographic survey supersedes all information of like nature on the uncorrected chart. 1. Letter all information.

2. In "Remarks" column cross out words that do not apply.
3. Give reasons for deviations, if any, from recommendations made under "Comparison with Charts" in the Review.

CHART	DATE	CARTOGRAPHER	REMARKS
5984	7/12/67	W.H. WALL	Pull Part Before After Verification Review Inspection Signed Via
			Drawing No. 23
5984	12/4/68	H.V. Howard	Rati-Part Baisse After Verification Review Inspection Signed Via
	/		Drawing No. 25
5984	11-14-69	BFernanders	Full Paralletere After Verification Review Inspection Signed Via
			Drawing No. 26
			Full Part Before After Verification Review Inspection Signed Viz
			Drawing No.
			Full Part Before After Verification Review Inspection Signed Via
			Drawing No.
			Full Part Before After Verification Review Inspection Signed Via
			Drawing No.
<u> </u>	 -		Full Part Before After Verification Review Inspection Signed Via
			Drawing No.
			Full Part Before After Verification Review Inspection Signed Via
			Drawing No.
	;; <u>;</u>		Full Part Before After Verification Review Inspection Signed Via
,			Drawing No.
			Full Part Before After Verification Review Inspection Signed Via
-	<u> </u>		Drawing No.
		,	
	···-		
_			

FORM C&GS-8352 SUPERSEDES ALL EDITIONS OF FORM C&GS-975

USCOMM-DC 8558-P63