

6249a
6249b

Graphic Control

Additional work

Diag'd. on Diag. Ch. No. 1265-2

Form 504
Rev. Dec. 1933
DEPARTMENT OF COMMERCE
U.S. COAST AND GEODETIC SURVEY
R. S. PATTON, DIRECTOR

DESCRIPTIVE REPORT

Topographic

~~Hydrographic~~

Sheet No. G (Front & Back)

State FLORIDA

LOCALITY

Intracoastal Waterway

Santa Rosa Sound

1934-5

CHIEF OF PARTY

L. E. Rittenburg

U. S. GOVERNMENT PRINTING OFFICE: 1934

6249a 6249b.

Additional work

Additional work

DEPARTMENT OF COMMERCE
U. S. COAST AND GEODETIC SURVEY

TOPOGRAPHIC TITLE SHEET

Additional work

Graphic control

T6249 a b

Each Topographic and Graphic Control Sheet, and each Air Photographic Drawing should be accompanied by this form, completed so far as practicable, when forwarded to the Washington office.

Additional work

Registry No. 6249 a&b

Field No.

Scale 1-10,000

State Florida General locality Santa Rosa Sound

Specific locality West of the Narrows

Dates: Survey began 25 Feb. 1946 Completed 1 March 1946

Photography 18 May 1945, Supplemented by ground surveys to 1 March 1946

Project No. Ph-1 (45) Instructions dated 7Dec45; Sup. 1, 28Dec45; Sup. 2, 5Jan46; Sup. 3, 31Jan46.

Vessel } or Shore Party Chief of party E. L. Jones

Field work by I. I. Saperstein Office work by I. I. Saperstein

Final inking by I. I. Saperstein

Ground elevations } in feet above { M. H. W.
Treetop elevations } or {Contours } by { Planetable } Interval _____ ft.
Approximate contours } Multiplex }
Form lines }

REMARKS

DESCRIPTIVE REPORT TO ACCOMPANY
TOPOGRAPHIC SHEET REGISTRY NO. 6249a, 6249b

PROJECT: Ph-1 (45) DATE OF INSTRUCTIONS: 7 Dec.45;Sup.1,
28 Dec.45;Sup.2,5 Jan.46;Sup.3,31 Jan.46

DATE OF FIELD WORK: 25 Feb. 46 to 1 Mar. 46.

PURPOSE: To locate on the sheet existing aids to navigation and make major topographic revisions where necessary in the original shore line and topographic detail.

FIELD WORK: The field work consisting of additions and corrections to the original survey have been shown on the sheet in orange ink to distinguish them from the original work. Only these corrections and additions are discussed in this report.

AIDS TO NAVIGATION: Were located by 3 or more planetable cuts.

MAJOR TOPOGRAPHIC CHANGES: There are no major topographic changes of significance to the 1:40,000 charts, on these sheets.

LANDMARKS, GEOGRAPHIC NAMES, COAST PILOT CORRECTIONS, RECOVERY OF HORIZONTAL CONTROL, MAJOR TOPOGRAPHIC CHANGES, HYDROGRAPHIC INFORMATION, FIELD INSPECTION OF PHOTOGRAPHS, and DISCREPANCIES IN PUBLISHED BRIDGE DATA have been made the subject of a special report and is submitted by areas for this project. The area of this sheet is covered in Special Report, Project Ph-1 (45), West Bay to Pensacola Bay Entrance.

DISCREPANCIES IN PUBLISHED DESCRIPTIONS OF AIDS TO NAVIGATION have been reported by letter to the Director in accordance with instructions. Copies of these discrepancies have been attached to the Special Report.

Submitted by

Irving I. Saperstein
Irving I. Saperstein

Approved and forwarded.

Edmund L. Jones
Edmund L. Jones
Chief of Party

DEPARTMENT OF COMMERCE
U. S. COAST AND GEODETIC SURVEY

U. S. COAST & GEODETIC SURVEY
LIBRARY & ARCHIVES

REG. NO.

APR 16 1935

Acc. No. _____

TOPOGRAPHIC TITLE SHEET

GRAPHICAL CONTROL SHEET

The Topographic Sheet should be accompanied by this form, filled in as completely as possible, when the sheet is forwarded to the Office.

Field No. G (front & back)

REGISTER NO.

6249a
6249b

State Florida

General locality Intracoastal Waterway

Locality Santa Rosa Sound

Long 86-57 to Upper Fritchard Long Point

Scale 1:10000 Date of survey Dec. - Jan, 19 34 - 5

Vessel Shore Party 15

Chief of party L. E. Rittenburg

Surveyed by A. O. Dority

Inked by A. O. Dority & L. E. Rittenburg

Heights in feet above _____ to ground to tops of trees

Contour, Approximate contour, Form line interval _____ feet

Instructions dated Nov. 30, 1934, 19 _____

Remarks: _____

DESCRIPTIVE REPORT SHEET NO. G (Front & Back)

See Descriptive Report Sheet No. F (Front & Back)
File No. 6250a & b

REVIEW OF GRAPHIC CONTROL SURVEY T-6249a, SCALE 1:10,000

Date of Review 11/17/36

1. This survey has been reviewed in connection with Air Photo Compilation Nos. T-5478, , , with particular attention to the following details:

- ✓(a) Projection has been checked in the Field.
- ✓(b) Accuracy of location of plane table control points.
- ✓(c) Discrepancies between detail on this survey and the air photo compilations listed above.
- ✓(d) Discrepancies found in descriptions submitted on Form 524 when compared with the air photo compilations listed above.

✓2. Refer to the reviews and descriptive reports of air photo compilations Nos. T-5478, , , for a more complete discussion of any errors or discrepancies found.

✓ Any material errors found on this survey are noted in subsequent paragraphs of this review, and these have been reported to the Field Records Section and the Cartographic Section.

✓ Notes and corrections resulting from the review are shown on this survey in green.

L. C. Landy
r B. Jones

REVIEW OF GRAPHIC CONTROL SURVEY T-62496, SCALE 1: 10,000

Date of Review 11/17/36

1. This survey has been reviewed in connection with Air Photo Compilation Nos. T-5478, 5477, , with particular attention to the following details:
- (a) Projection has been checked in the Field.
 - (b) Accuracy of location of plane table control points.
 - (c) Discrepancies between detail on this survey and the air photo compilations listed above.
 - (d) Discrepancies found in descriptions submitted on Form 524 when compared with the air photo compilations listed above.
2. Refer to the reviews and descriptive reports of air photo compilations Nos. T-5478, 5477, , for a more complete discussion of any errors or discrepancies found.
- Any material errors found on this survey are noted in subsequent paragraphs of this review, and these have been reported to the Field Records Section and the Cartographic Section.
- Notes and corrections resulting from the review are shown on this survey in green.

L. C. Landy

✓ B. G. Jones

REVIEW OF GRAPHIC CONTROL SURVEY T-6249^a, SCALE 1:10,000

Date of Review 12/2/36

1. This survey has been reviewed in connection with Air Photo Compilation Nos. T-5479, , with particular attention to the following details:

- ✓ (a) Projection has been checked in the Field.
 - ✓ (b) Accuracy of location of plane table control points.
 - ✓ (c) Discrepancies between detail on this survey and the air photo compilations listed above.
 - ✓ (d) Discrepancies found in descriptions submitted on Form 524 when compared with the air photo compilations listed above.
- ✓ 2. Refer to the reviews and descriptive reports of air photo compilations Nos. T-5479, , for a more complete discussion of any errors or discrepancies found. *Minor discrepancy in location of section of H.W.L.*
- ✓ Any material errors found on this survey are noted in subsequent paragraphs of this review, and these have been reported to the Field Records Section and the Cartographic Section. *None*
- ✓ Notes and corrections resulting from the review are shown on this survey in green.

Frank R. Gollon