Form 504
Rev. April 1935
DEPARTMENT OF COMMERCE U. S. COAST AND GEODETIC SURVEY

# DESCRIPTIVE REPORT 6792 A Topographic | Sheet No. 6792 B Rudrographic

U. S. COAST & GEODETIC SURVEY

LIBRARY AND ARCHIVES

MAY 19 1941

Acc. No.

State Alabama and Florida

LOCALITY

## DEPARTMENT OF COMMERCE -U. S. COAST AND GEODETIC SURVEY

## TOPOGRAPHIC TITLE SHEET

The Topographic Sheet should be accompanied by this form, filled in as completely as possible, when the sheet is forwarded to the Office.

Field No.

REGISTER NO. T-6792 a and b Captic Contra
State Florida and Alabama
General locality Gulf Coast
Locality Perdido Entrance
Scale 1:20,000 Date of survey FebMarch , 1940
Vessel Ship HYDROGRAPHER (Launch FARIS)
Chief of party G: C. Mattison
Surveyed by E. B. Lewey
Inked byC. W. Clark
Heights in feet above to ground to tops of trees
Contour, Approximate contour, Form line interval feet
Instructions dated June 21, , 19 39
Remarks:

267

### DESCRIPTIVE REPORT

#### TO ACCOMPANY

#### TOPOGRAPHIC SHEETS T-6792A and T-6792B

### PROJECT HT-236

#### 1940

#### INSTRUCTIONS:

These surveys were executed in accordance with Directors Instructions for Project H. T. 236, as follows:

Instructions dated June 24, 1939

Supplemental Instructions dated July 1, 1939

Supplemental Instructions dated Oct. 13, 1939

Supplemental Instructions dated January 31, 1940

## GENERAL DESCRIPTION OF COAST:

These surveys were executed primarily for location of signals for control of hydrography in the Gulf. The shore line was not surveyed. This area is covered by air photo compilations from photos made in 1934 and the coast is described adequately in the Coast Pilot.

#### LANDMARKS:

No landmarks suitable for navigation, other than aids to navigation at Perdido Entrance, were located.

#### COMTROL:

Control was based on a scheme of second-order triangulation executed in 1934. Sufficient stations were recovered so that no new

control was required. Only those stations which were useful for the work done are plotted on the sheets.

## SURVEY METHODS:

Stnadard topographic survey methods were used. Signals were located by stadia traverse supplemented by resection and intersection methods. All traverses closed within the allowable limits for the scale of the sheet and were adjusted when necessary in accordance with page 57 of the Topographic Manual.

## COMPARISON WITH PREVIOUS SURVEYS:

Surveys of the shore line were not required by the instructions and none were made. The shore line shown on these sheets in pencil was transferred from air photo compilations sheets T-5490, T-5494, T-5495, and T-5498. No changes were made in the shore line as transferred form those sheets. Comparison of shore line was made by visual inspection only and no changes were noted.

Aids to navigation at Perdido Entrance not on previous surveys were located on Sheet #6792 A.

The only changes in topography made on the sheets is the addition of a small building on sheet #6792 B at Gulf Beach and the deletion of two buildings slightly farther east which are shown on air photo compilation T-5494. The new building added is shown in ink at 30-17.83, 87-25.62, inside the circle at  $\Theta$  Pol. There is no change in the large concrete structure on which  $\triangle$  Gulf Beach 1934 is located.

## GEOGRAPHIC NAMES:

No new geographic names were used on the sheet.

Respectfully Submitted,

Charles W. Clark, Aid, Coast and Geodetic Survey,

Forwarded:

W. M. Scaire, Chief of Party,

Commanding HYDROGRAPHER

No review wecessay RH. Cavalene 12/8/92

## LIST OF SIGNALS

## To Accompany

## DESCRIPTIVE REPORT FOR TOPOGRAPHIC SHEETS

## T-6792 a and b

## SHEET T-6792a

## TRIANGULATION STATIONS:

1. B am, 1919 -	Temporary wooden signal.
2. B. P. 6 (U. S. E.) - 1934	Temporary wooden signal.
3. John, 1934	Temporary wooden signal.
4. Low grey tank, 1934	
5loon, 1934	No signal over.
6. Nimpy, 1934	Temporary wooden signal

## TOPOGRAPHIC STATIONS:

1. Bayou St. John Entrance Light ( @ Lig.)	Light in water	Recoverable		
2. Bayou St. John West Beacon 2	Beacon in water	Recoverable		
3. B. P. 5 (U. S. E.)	Temporary wooden signal.	Recov erable		
4. Perdido Entrance Front Range Beacon	PIGHAI.	Recoverable		
5. Perdido Entrance Rear Range Beacon		Recoverablo		
6. Perdido Entrance Buoy	Buoy in water	Not recoverable		
7. Perdido Entrance Buoy 2	Buoy in water	Not recoverable		
8. Prominent twin trees ( O Prom)		Not recoverable		
9. Lee	Temporary wooden	Not recoverable		
10. Lest	signal Tree	Not recoverable		
11. Low	Temporary wooden signal	Not recoverable		
12. Stac	Stack on small house	Not recoverable		

13. Stake

Post on beach

Not recoverable

14. Web

Temporary wooden signal

Not recoverable

15. Mindmill ( @ Mill)

Windmill

Recoverable

All stations on land except as noted.

#### SHEET T-6792 b

## TRIANGULATION STATIONS:

1. Gulf Beach, 1934.

Temporary wooden signal

on structure.

2. John, 1934.

Temporary wooden signal.

3. Lag "A", 1934.

Temporary wooden signal.

4. Lagoon "B", 1934.

Temporary wooden signal.

5. Old, 1934.

Temporary wooden signal.

6. Pensacola-Mobile Bn. 13, 1934.

Light in water.

7. Pensacola-Mobile Bn. 15, 1934.

Light in water.

## TOPOGRAPHIC STATIONS:

1. Bum.	Temporary wooden signal	Not recoverable
2. Cow	Tree	Not recoverable
3. Dub	Temporary wooden signal	Not recoverable
4. Lest	Tree	Not recoverable
5. Lit	Temporary wooden signal	Not recoverable
6. Lou	Temporary wooden signal	Not recoverable
7. Low	Temporary wooden signal	Not recoverable
8. Pol	Power line pole	Not recoverable
94 Raf	Temporary wooden signal	Not recoverable
10. Win	Tree	Not recoverable

All stations on land except aids to navigation.

Remarks

**Decisions** 

		<del>,</del>
1		302875
2		եղ
3		302874
4		302875
5	·	
6		1
	·	
8	·	
9		
10		
11	,	
12		
13		
14		
15		
16		
17		
18		
19		
20		
21		
22		
23		
24		
25		
_26		
27		
M 234	<u>.</u>	

GEOGRAPHIC NAMES Survey No. T67	109 .	lib /	Or 40 C	S. Mod.	ris de la companya de	T Mos	S. Carlos	Mod Media	J.S. Jugar	ž /.
		Ou Mo.	0. 40. 0	1.3 Mg.	de region de	or led wee	2.0.SV	Sough.	25.	
Name on Survey	A,	<u>В,</u>	<u> </u>	D	/ E_	/ F	G	<u>/ н</u>	/ K	
Alabama Point							<u> </u>			1
Florida Point	-					-				2
Gulf Beach					ļ	<u> </u>	<u> </u>			3
Perdido Entrance						ļ	ļ			4
							-	<u> </u>	1	5
		,							<u> </u>	6
			<u>,                                     </u>		<del>\(\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \</del>	9/4/	<u> </u>			7
			ty L	HEL	1 0	,,,,,				8
			,							9
										10
										11
				1	<del> </del>	<u> </u>				12
				<u> </u>						<u> </u>
						+			<u> </u>	13
			<del> </del>			<u> </u>	<u> </u>	<u> </u>	-	14
						-				15
		_		<u> </u>	-	-			<u> </u>	16
						-				17
										18
										19
							Ē			20
							!			21
										22
										23
<del> </del>										24
						† · · ·				•
			<del>                                     </del>							25
	<del>                                     </del>									26
		+		-			<u> </u>			27 M 234

# MEMORANDUM IMMEDIATE ATTENTION

,		-	received May 20, 1941
SURVEY	Nexxkix		registered June 5, 1941
DESCRIPTIVE REPORT >	> ANDAANN	≺	verified
RHOIDSTAIXOE	No. T	T6792a&b	reviewed
,		Caphic Com	approved

This is forwarded in order that your attention may be directed to the matters as indicated below. Please initial in column 3 as an acknowledgement that your attention has been thus directed. The complete original records are available if desired. If you cannot give this your immediate attention, please initial, note, and forward to the next section marked, calling for the records at your convenience.

ROUTE	Initial	Attention called to
20		:
22		
24		
25		
26		
30		
40		
62	-	
63		
82		
83		
88		
90		
		·

RETURN TO

82 T. B. Reed

1 gosa