12988

Diag. Cht. No. 1254.

U. S. DEPARTMENT OF COMMERCE COAST AND GEODETIC SURVEY

DESCRIPTIVE REPORT

Type of Survey Chart Topography

Field No. Ph-6605 Office No. T-12988

LOCALITY

Florida

Caxambas Pass to

General locality Fakahatchee Pass

Locality Cape Romano

NOV 19...65.-JULY 1967

CHIEF OF PARTY W.H.Shearouse, Chief of Party V.R.Soberalski, Photo. Office Rock-- ville, Md.

LIBRARY & ARCHIVES

DATE ...

December 1967

сомм-рс 61300

	DESCRIPTIVE RE	T - 1298		
PROJECT NO. (II):				
рн-660	05			
FIELD OFFICE (11):			CHIEF OF PARTY	
			W. H. Shearou	se
PHOTOGRAMMETRIC OFFICE (II			OFFICER-IN-CHARGE	
ESSA Headquarte Rockville, Mary			V. Ralph Sobi	eralski
INSTRUCTIONS DATED (II) (III):	<u> </u>			· · · · · · · · · · · · · · · · · · ·
Aerotria	February 8, 1965 a ngulation: Mayrl2 mmetric Office: N I	2 , 1966	1966: June 13, 19	66 and
B-8 Stereoplot	ter and Graphic	STEREOSC	COPIC PLOTTING INSTRUMENT	SCALE (III):
1:40,000			1:30,000	
DATE RECEIVED IN WASHINGTO		DATE:	DATE RE	EGISTERED (IV):
				· · · · · · · · · · · · · · · · · · ·
GEOGRAPHIC DATUM (III): N.A. 1927			VERTICAL DATUM (III): MEAN SEA LEVEL EXCEPT Elevations shown as (25) refe Elevations shown as (5) refe i.e., mean low water or mean	er to mean high water r to sounding datum
REFERENCE STATION (III):				
REFERENCE STATION (III): JOHNSON, 1887				
JOHNSON, 1887	LONG.:			
JOHNSON, 1887	LONG.: 81°41°40.466	6"	ADJUSTED UNADJUSTED	
JOHNSON, 1887	Ì	6"	=	ZONE

DESCRIPTIVE REPORT - DATA RECORD

DATE: FIELD INSPECTION BY (II): 11/3/65 W. H. Shearouse (premarking control) MEAN HIGH WATER LOCATION (III) (STATE DATE AND METHOD OF LOCATION): March, 1967 Mean-high-water located photogrammetrically using B-8 stereoplotter DATE OF PHOTOGRAPHY - NOVEMBER 1965 DATE PROJECTION AND GRIDS RULED BY (IV): May 1966 R. A. Lillis PROJECTION AND GRIDS CHECKED BY (IV): June 1, 1966 R. K. DeLawder DATE CONTROL PLOTTED BY (III): February 1967 J. A. Mooney CONTROL CHECKED BY (III): February 1967 J. H. Taylor DATE RADIAL PLOT OR STEREOSCOPIC CONTROL EXTENSION BY (III): February 15, 1967 I. I. Saperstein DATE STEREOSCOPIC INSTRUMENT COMPILATION (III): PLANIMETRY March 1967 CONTOURS J. C. Richter MANUSCRIPT DELINEATED BY (III): March 1967 J. C. Richter SCRIBING BY (III): PHOTOGRAMMETRIC OFFICE REVIEW BY (III): September 1967 J. P. Battley, Jr. REMARKS:

Field Edit by:

W. H. Shearouse July 1967

DESCRIPTIVE REPORT - DATA RECORD

AMERA (KIND OR SOURCE) (III):

(L) RC-8 (infrared and color) and (M) RC-9 (color)

	Pt	(OTOGRAPHS (III)		
NUMBER	DATE	TIME	SCALE	· STAGE OF TIDE
65-L-9274-9280 65-L-9267-9272 65-L-9332-9337 65-L-9292-9299 65-L(C)-9229-9237 65-L(C)-9220-9225 65-L(C)-9217-9219 65-M(C)-957-960 65-M(C)-964-967	11/21/65 11/21/65 11/21/65 11/21/65 11/20/65 11/20/65 11/20/65 11/21/65	12:20 12:16 13:09 13:57 10:47 10:42 10:37 8:53 9:16	1:33,000 1:33,000 1:33,000 1:33,000 1:20,000 1:20,000 1:20,000 1:60,000	4.30 4.10 2.99 (substa. MARCO 4.10 not used for shore- line delineation """"""""""""""""""""""""""""""""""""
		I .	computation	s based on actual Ref. Sta.
		TIDE (III)	· · · · · · · · · · · · · · · · · · ·	

		RATIO OF RANGES	MEAN RANGE	SPRING RANGE
REFERENCE STATION: ST. MARKS			2.4	diurna 3.3
MBORDINATE STATION: COON KEY			2.6	3.5
SUBORDINATE STATION: CAPE ROMANO			2.6	3.5
WASHINGTON OFFICE REVIEW BY (IV):		DATE:		
PROOF EDIT BY (IV):		DATE:		
NUMBER OF TRIANGULATION STATIONS SEARCHED FOR (II): *25	RECOVERED:	identifie	o: premar	ked)
NUMBER OF BM(S) SEARCHED FOR (II):	RECOVERED:	IDENTIFIE	D	

NUMBER OF RECOVERABLE PHOTO STATIONS ESTABLISHED (III):

None

NUMBER OF TEMPORARY PHOTO HYDRO STATIONS ESTABLISHED (III):

None

REMARKS:

^{*}denotes control located for entire project, including Surveys T-12986, T-12988, T-12989 and T-12990

SUMMARY TO ACCOMPANY DESCRIPTIVE REPORT T-12986, T-12988, T-12989 and T-12990 Job PH-6605 September 1967

This project is comprised of four maps, compiled to provide the base for new Chart 642-86. Chart 642-86 will be published at 1:40,000 scale and covers the coastline of the Gulf of Mexico and bordering inland waterways from Naples to Lostmans River, Florida. The area is currently covered by 1:80,000 scale Conventional Charts 1253 and 1254.

Field inspection was accomplished during October 1965 and was limited to the premarking of horizontal central prior to flying the bridging photography.

The area of these surveys was flown November 20 and 21, 1965.

As a result of higher priority projects, completion of bridging for this project was delayed until January-February 1967. Five strips of 1:60,000 scale color photographs were bridged by analytic aerotriangulation methods.

The manuscripts were compiled in the Washington office using the photogrammetric instructions for compiling topography to chart scale. Compilation was achieved on the B-8 stereoplotter utilizing 1:60,000 scale color photography and 1:40,000 scale infrared photography. Color prints at 1:20,000 scale were also available to office identify aids and landmarks, but the majority of the aids to navigation had to be located by field methods during field edit.

Field edit was accomplished in June-July 1967. It encompassed the verification of compiled features, the location and/or verification of all sids to navigation and landserks and a geographic names investigation.

Application of field edit corrections and additions, including a plethors of daybeacons and lights, was completed by the Washington compilation office in August 1967. Mineteen pages of Forms 567 were listed, scaled and submitted to the Marine Chart Division for the positioning of landmarks and side to navigation.


A "Chart Division Manuscript Copy" of each manuscript was supplied the Marine Chart Division prior to the application of geographic names.

A "Registration Manuscript Copy" will be registered in the Bureau Archives under their respective T-numbers. Czalid copies of these were also sent to the Marine Chart Division.

Submitted by:

Jeter P Battley, Ir

Jeter P. Battley, Jr.



JOB PH-6605

Lostmans River to Naples, Florida (Chart 642-SC)

In accordance with Instructions dated July 30, 1965, required stations have been premarked during the period October 4 through 29, 1965. Through courtesy extended by the Rangers of the Everglades National Park, headquarters were maintained at their boat basin at Everglades City, throughout the job.

1. METHODS)

Unbleached muslin was used for all stations as the white polyethylene plastic sheeting could not be obtained in the Miami area, nor could the VisQueen factory in Flemington, M. J. furnish it in the desired thickness. Targets were made with a triangle 12 feet on the side, for the stations. A triangular frame was constructed of 1"x 4"x 12' boards and centered over the station mark, covered with precut cloth, and staked to the ground. 13 stations were thus marked; 3 were premarked by the substitute station method. (There is one exception to centering the triangle over the station mark: Private survey station CT 125, COLLTER PROPERTIES, 1962 was premarked with station mark at apex of triangle. It is so shown on the OSI card.) All wing panels are the 25-foot runner type, the signal cloth being 36/38 inches wade. Target in the examples furnished with Job Instructions-was used in all but three instances, the variations being clearly shown in the sketches on Form 152Is.

Station JOHNSON, 1887, is located under the steps leading to an observation tower. The southeast corner of the tower was located as a substitute station. The tower is 17 feet high, 18 feet square and is gray with a white guard rail around its top. It should show well on the photographs.

Station ONION, 1928, was double-premarked. That, is, a triangle was centered over the station and one placed some

50 feet to the west, angle and distance being recorded to the west, or substitute one. Onion Key, on which the station is located, is an Indian mound and the Park Service Authorities requested that we not cut anymore vegetation than necessary. In order to eliminate possibility of shadow interference, the foregoing plan was used.

2. HISTORY

Stations originally called for to be premarked were BROAD, FIG, ONION, SEMINOLE, PAVILION KEY, LOPEZ, EVERGLADES, GOMEZ, ROYAL PAIM, CAPE ROMANO, SOUTH BASE, MEADE, and MAPIES. Of these, GOMEZ, CAFE ROMANO and SOUTH BASE are destroyed. The others have been premarked. Subsequent oral instructions said to premark FANKA and BEACH. BEACH is destroyed; FANKA was premarked.

Several of the stations are in heavily wooded areas. No suitable nearby place was available for a substitute station, so the trees were cleared at the station site. Special attention was paid to shadow problems and it is believed these have been overcome, especially if the photos are taken between 9 AM and 3/3:30 FM.

During the course of work, it was discovered that Johnson-Hall & Associates, Inc., Land Surveyors and Civil Engineers, of Fort Myers, Florida, had established second order Geodimeter traverse control in the Cape Romano-Marco Island area, which traverse originated and ended on Coast and Geodetic Survey stations. In lieu of destroyed stations CAPE ROMANO and SOUTH BASE, three of these stations were premarked. They are GT 128, COLLDER PROPERTIES, 1962, GT 129, COLLTER PROPERTIES, 1962, and REFERENCE MONUMENT NO. 4, COLLIER FROPERTIES, 1965. Information on these stations and other parts of the Johnson-Hall work, is being forwarded with Job data. Their work appears to have been carefully and accurately done. Should the stations submitted, prove accurate for our purposes it would be well to keep in mind, as they have established similar control north and south of Fort Myers along the coastline for a con- . siderable distance, I am informed.

While recovering station JOHNSCN, 1887, a nearby station—COLLER ERDL, 1960—was found. No information was furnished for this C&GS station nor does it appear on the triangulation diagram. Florida Vol. II, INDEX HORIZONTAL CONTROL DATA, was

not furnished, in which the station is described. COLLIER, 1960, is being used by an oil exploration company as a LCRAC station site. They have a 145 foot radio entenna erected on it. This station is located in a white sand area and while it was not called for in the instructions, as an experiment, it was premarked with orange-colored signal cloth. It is located about 260 feet south of JOHNSON, 1887.

3. SUMMARY

Coast & Geodetic Survey stations searched for: 22 Recovered: 15

Premarked: 13

Lost or destroyed: 7.

Private survey stations premarked: 3.

Respectfully submitted, 11/3/65.

William H. Shearouse, Chief, Photo Party 751

PHOTOGRAMMETRIC PLOT REPORT JOB PH-6605 NAPLES TO LOSTMANS RIVER, FLORIDA

February 15, 1967

21. Area Covered

This report covers an area from Naples to Lostmans River, Florida, consisting of three (4) 1:40,000 scale T-sheets -- T-12986, F and S. T-12989 and T-12990. N and S.

22. Method

Analytic aerotriangulation methods were used to bridge five strips of 1:60,000 color "M" photography. Control was not furnished for the southeast terminals of Strips 3 and 4; Strip 4, therefore, was tied to Strip 1 and Strip 3 was tied to Strip 4 by common passpoints built up from Strip 1.

The attached sketch shows the strips bridged and the placement of triangulation furnished that was used in the final adjustment.

Mercator coordinate values have been furnished for all bridge points on the IBM readout.

23. Adequacy of Control

Most horizontal control was premarked with white panels; although, several control stations were identified by the substitute station method.

Premarked station BROAD 1928 could not be seen on the photographs. Station FIG 1887 was therefore used as a terminal for Strip 2.

A memorandum from Mr. Richard Stokes, The District Ranger, Everglades National Park, indicates the possibility that the target at ONION 1928 had been disturbed prior to photography. This station was used as the terminal on Strip 1. The substation for ONION was not used in the adjustment but was merely a "floater" and held very well. However, common tie points between Strips 1 and 2 in the vicinity of ONION did not agree by about 25 feet. This discrepancy could not be resolved without field investigation. Nonetheless, it is believed that the bridge is adequate for 1:40,000 scale chart compilation.

The control used in the final adjustment is adequate. Closures to control have been tabulated and are part of this report.

The high-water line or marsh was used for vertical control needed for the adjustment.

25. Photography


The definition and quality of the color diapositives were very poor as these photographs were taken under adverse conditions.

Respectfully submitted:

Irving I. Saperstein

Approved and Forwarded:

Henry P. Eichert



COMPILATION REPORT T-12988

31. Delineation

Both graphic and instrument methods were used to compile this manuscript. Color plates at a scale of 1:60,000 were set on the B-8 stereoplotter. The manuscript was then partially compiled at the required 1:40,000 scale. Using this partial compilation for control, the manuscript was completed graphically using infrared photography ratioed to manuscript scale.

32. Control

Identification, density and placement of control were adequate.

33. Supplemental Data

None

34. Contours and Drainage

Contours - inapplicable; Drainage - all drainage has been shown.

35. Shoreline and Alongshore Details

Shoreline was office interpretated using infrared photography. No field inspection was available. The quality of the 1:60,000 color photography was so poor that no shoal or channel lines could be identified.

36. Offshore Details

The structure shown offshore in Caxambas Pass was known as Caxambas Pass Light; however, this light is no longer operating and is not listed in the light list.

37. Landmarks and Aids

No landmarks or aids could be identified on the photography. Forms 567 are submitted for one landmark and 40 aids that fall within the limits of this manuscript and are to be located during field edit.

38. Control for Future Surveys

None

39. Junctions

Junction has been made and is in agreement with T-12986 to the north and T-12989 to the east. To the south and west are all water areas.

40. Horizontal and Vertical Accuracy

No comment

41. - 45.

46. Comparison with Existing Maps

Comparison has been made with C&GS Surveys T-4371 and T-4430, scale 1:20,000, dated February 22, 1967, and Hydrographic Surveys H-5072 and H-5065.

47. Comparison with Nautical Charts

Comparison has been made with Nautical Chart No. 1254 (Chatham River to Clam Pass), scale 1:80,000, 5th Edition, April 26, 1965.

Submitted by:

Jacqueline B. Phillips
J. B. Phillips

Approved by:

K. N. Maki

FIELD EDIT REPORT, JOS PH-6605 (Chart 642-SC)
MAPS T-12986, T-12988, T-12989, T-12990

In accordance with Field Edit Instructions dated May 5, 1967, reference C1413.

51. METHODS

All major rivers, creeks and passages were ridden out to verify delineation of shoreline, existence of small keys and islets, and for addition of low-water and shoal features where practical:

Areas of Maps T-12990 and T-989 lying within the Everglades National Park were gone over with the District Park Ranger for his comment and suggestions.

Many sids to navigation could not be positively identified on the photographs. These and other chartable features such as piles and stakes, were located by sextant fix or theodolite cuts. Cojects for the fixes and points occupied for cuts, were identifiable images pricked on the 1:40,000 scale ratio infrared photographs. These were numbered 90-A, B, etc., 89-A, B, etc., 83-A, B, etc., and 86-1, 2, etc., to denote what map the photopoint is in. A short description will be found on the photographs or in the sketchbook. Fixes are recorded in 2 sketchbooks, numbered 1 and 2.

Due to the nearness of the photo points to most of the daybegcons-caused by narrow streams in which the aids are locatedpractically all the fixes had to be plotted on pages of paper, which were oriented under the cronaflex print of the map manuscript, thus determining the position of the aid. The point was then pricked and labelled. These pages of graphic fixes are submitted.

In some areas the image of the daybeacons could be seen on

the 1:20,000 scale transparencies. These were marked direct and cross-reference made on the Field Fdit Sheet or cronaflex.

A number of aids to havigation were office identified, positions scaled and Form 567 made. Identification of a few of these was incorrect. (See the Gronaflez for correct position.) All others were visually verified, dates being noted on Form 567.

No positions were scaled in the field. However, Form 567 is submitted, accounting for all nonfloating aids to navigation (and Landmarks).

Additions, corrections and deletions have been noted on the THELD EDIT SHEET-DISCHEPANCY PRINT with cross-feferencing to the photographs by number.

Violet ink was used for field edit notes.

In addition to the Field Edit Sheet and Gronaflex for each map, field edit information will be found for Map T-12990 on photographs: 65M(c)1000 thru 1005, 1022, 1023, 1024, 1026; and ratioed infrared 65L9367R, 9368R, 9372R, 9373R, 9374R, 9404R, and 9411R.

For T-12989: 65M(c)968 thru 972, 986, 1028; ratioed infrared 65L9337R, 9345R, 9346R, 9377R, 9398R, 9399K; and certain ones of the 1:20,000 scale color transparencies 9238 thru 9255.

For T-12988 and T-12986: 1:20,000 color transparencies 6519198 thru 9202, 9207 thru 9215, 9221, 9225, 9231, 9233, 9235, 9236, 9237; and, ratioed infrared 6519264R, 9268R, 9269R, 9270R, 9276R, 9278R, 9279R thru 9282R, 9285R, 9293R, 9294R, 9295R, 9328R, 9335R, and 9237R.

52. ADEQUACY OF COMPILATION

These maps are well-compiled. After application of field edit information they will be adequate.

53. MAP ACCURACY

No tests were specified.

54. RECOMMENDATIONS

None offered.

55. FMAMINATION OF PROOF COPY

Hot required.

GEOGRAPHIC NAMES

This is the subject of a special report.

Submitted 7/10/67

William H. Shearouse

William H. Shearouse Chief, Photo Party 60

REVIEW REPORT T-12988 (Chart 642-SC) Chart Compilation September 1967

61. General Statement

(see Summary)

62. Comparison with Registered Topographic Surveys

Comparison was made with surveys T-4371 and T-4430, scale 1:20,000, dated February 22, 1927. These surveys are superseded by T-12988 (in their common area) for nautical charting.

63. Comparison with Maps of Other Agencies

None - USGS quadrangle coverage stops at the northern limits of this manuscript.

64. Comparison with Contemporary Hydrographic Surveys

Comparison was made with surveys H-5072 and H-5065, scale 1:20,000, dated 1930.

65. Comparison with Nautical Charts

Comparison was made with chart number 1254 (Chatham River to Clam Pass), scale 1:80,000, 5th Edition, dated April 26, 1965. All differences, noted on the discrepancy print between the published chart and the new survey, were resolved during field edit. A copy of manuscript T-12988 with field edit corrections and additions applied was furnished to the Small Craft Chart Branch prior to review. No changes of consequence to nautical charting were made during review.

66. Adequacy of Results and Future Surveys

The four maps of this project comply with project instructions and are within the National Standards of Map Accuracy.

Reviewed by:

Approved by:

Chief, Photogrammetric Branch

Chief, Photogrammetry Div.

11-27-67

Jeter P. Battley Jr

Chief, Marine Chart Div.

GEOGRAPHIC NAMES

FINAL NAME SHEET

PH-6605 (Lostmans River, Fla.) T-12988

Addison Bay

Barfield Bay

Big Marco Pass

Blackwater River

Buttonwood Bay

Cape Romano

Caxambas Bay

Caxambas Pass

Clam Bay

Collier Bay (Changed from Smokehouse Bay)

Coon Key

Dickman Point

Dismal Key

Dismal Key Pass

Fish Hawk Creek

Fred Key

Goodland

Goodland Bay (Add to Chart 1254)

Grassy Bay

Gullivan Bay

Helen Key

Horr Island

Johnson Bay

Kice Island (Add to Chart 1254)

Little Grassy Bay

Marco

Marco Island

McIlvaine Bay

Morgan Bay

Morgan Pass

Mud Bay

Palm Bay

Pig Key

Roberts Bay

Smokehouse Bay (Move slightly southward)

Sugar Bay (Add to Chart 1254)

Tarpon Bay

Ten Thousand Islands

White House Key (Changed from Horse Key)

Whitney River

Approved by:

A. Jøseph Wraight Chief Geographer

Prepared by:

Cartographic Téchnician

T-12988 Supplemental Name List

Blind Pass

Gomez Point

Hog Key

Royal Palm Hammock

Approved by:

Prepared by:

A. Joseph Wraight Chief Geographer

Cartographic Technician

19 67

July 5

Chief of Party.

William H. Shearouse

C&GS ro

NONFLOATING AIDS OR L'ANDMEARKS FOR CHARTS Maples, Ma. STRIKE OUT TWO TO BE CHARTED TO BE SEEN TO BE SE

I recommend that the following objects which have (have tight) been inspected from seaward to determine their value as landmarks be charted on (deleted strong) the charts indicated.

Davis L.H. The positions given have been checked after listing by

CHARTING NAME	FLORIDA			-					4			
CHARTING NAME Light			5	LATTRUDE#	LONG	LONGITUDE &		LOCATION	L O	OKK C	HOR.	CHARTS AFFECTED
Light	DESCRIPTION	SIGNAL NAME		D.M. METERS	,	D. P. METERS	DATUM	BURVEY No.	LOCATION		2410	
	GOOM KEY LIGHT		25-52	52.394	81-37	57.655	1927 1927	noso .1 T-12988	79/1/9	×	-	1254
	CAXALIBAS BAY										 	
Dayen 2	South Approach		25-53	150.1	. 8138	37.610 1047.0	u .	=	=	54		=
177	South Approach		25-53	16.318	\$1-39	176.95	a ,	==	=	м		=
	Caxambas Bay		25-53	54.542	, 51−39	38.119	ž.	Ħ	= ·	\ -¢		=
= 3	11		25-54		07-18	34.604 963.2	11	ı	==	ы		=
= ·	11		25-54	87.9	81-40	58,175	11	22		М		=
=			25-54	~	27-42	18.872	=	#	t.	ы		=
1:			25-54	02.343	177-18	19.734	E	æ	=	М		=
· t0			25-54	04.683	81-41	32.957.	Ħ	11	2 .:	प्र		=
6	=======================================		25-54	188.1	81-41	32.813 913.3	=	=	=	*		=
" 11	#		25-54	0	31-41	38.849	=	±	=	74		::
= 13	11 11		25-54	13.782	81-41	38.993 1085.3	2 2	=	=	×		=
77	=		55- 53	15.992.	31-41	37.268 7037.3	E	= 1	=	×	_	=

USCOMM.DC 16234-P61 (6 This form shall be prepared in accordance with Hydrographic Manual, Publication 20.2, Sec. 1-55, 2-39, 6-36, 7-18 to 22 inclusive, and Fig. 79. Positions of charted The data should be landmarks and nonfloating aids to navigation, if redetermined, shall be reported on this form. Revisions shall show both the old and new positions. considered for the charts of the area and not by individual field survey sheets. Information under each column heading should be given.

TABULATE SECONDS AND METERS



U.S. DEPARTMENT OF COMMERCE COAST AND GO ETIC SURVEY

NONFLOATING AIDS OR LIANDMARKEEFOR CHARTS

STRIKE OUT TWO TO BE DECETED. TO BE CHARTED TO SEVISED.

19.67

Naples , Fla.

I recommend that the following objects which have (Harelinal) been inspected from seaward to determine their value as landmarks be charted on (defered from) the charts indicated.

I. H. Davie The positions given have been checked after listing by

					1	POSITION			METHOD		TRA	(NAN-
BYATE	FLOKLDA			LATI	LATITUDES	TONG	LONGITUDE		LOCATION	07	2 180 12 409	CHARTS AFFECTED
CHARTING NAME	ă	DESCRIPTION	BIGNAL	. 0	" D.M.METERS		D. P. METERS	DATUM	BURVEY No.		HSHI	1110
	CAKAMBAS	BaY .										
Daybn 1	=	#		25-54	18.721	31-41	38.562	N.A. * 1927	noto ri T-12988	6/7/67	M	1254
v. 16	=	12		25-54	21.972	S1-41	36.406	=	=	u	34	=
11 17	=	. 11		25-54	27.321.	81-41	38.562 1073.3	. 11	=	12	5	=
10 =	=			25-54	30.421	27-77	37.556	==	=	=	5:1	=
19	*	11		25-54	26,781	81-41	41,437	11	ı.	11	М	=
	CAKAMBAS PASS	S PASS										
4 "	11	-		25-54	27.951	31-42	57.611	=	=	6/3467	54	¥
= 6	=	=		25-54	27.561 848.1	81-42	39.790	=	=	=	ы	=
	BIG MARCO RIVER	RIVER										
2 =	=:	=======================================		25-54	19.9	81-38	16.914-	÷	=	6/16/63	5-1	=
= 3	=	-		25-54	36,921	81-38	17.920 498.8	=	=	E.	×	=
. 7	=	=======================================		25-55	07,219	\$1-38	22.232	=	=	=	54	=
= 70	=	=		25-58	15,136	81-33	38.529	=	=	=	×	=

. USCOMM-DC 16234-P61 This form shall be prepared in accordance with Hydrographic Manual, Publication 20.2, Sec. 1-55, 2-39, 6-36, 7-18 to 22 inclusive, and Fig. 79. Positions of charted landmarks and nonfloating aids to navigation, if redetermined, shall be reported on this form. Revisions shall show both the old and new positions. The data should be considered for the charts of the area and not by individual field survey sheets. Information under each column heading should be given. * TABULATE SECONDS AND METERS.

U.S. DEPARTMENT OF COMMERCE TIC SURVEY

Cags Fo



19_67

COAST AND GE

NONFLOATING AIDS OR LANDMARKS FOR CHARTS

mīr s	
Manles Fla	
STRIKE OUT TWO	
TO BE CHARTED XXXIQIBEREY(5EQ)	1

I recommend that the following objects which have (have inspected from seaward to determine their value as landmarks be charted on (deleted from), the charts indicated.

The positions given have been checked after listing by L.H. Davis

					a.	POSITION			METHOD		THAN	
БТАТШ	FLOHIDA			15	LATITUDE*	LONG	LONGITUBE		LOCATION		HORE CHOSE	CHARTS
CHARTING	-	DESCRIPTION	BIGNAL	•	O.M. METERS	0	D.P. MEYERS	ратим	BURVEY No.	TOCK INCH	нѕиі	
	BIG MAR	MARCO RIVER										
Daybn 7	=			25-55	33.463	81-38	36.173	1927	020 FIO	6/19/67	54	7521
±30 =	=	11		25-55	11.	81-33	1262,6	ï	II.	11	×	=
10 10	=	11		25-55	ــــــــــــــــــــــــــــــــــــــ	61-39	03,625	=	H	Ξ	ьч	=
12	- 11	=		25-55	47.890	31-39	12.967	Ξ.	11	#	54	e .
76 1	=	11		25-55	50.360	31-39	13.686	н	12	=	. ₩	=
. " 15	п	11		25-56 7	02.577	81-39	4.16.8	=	=	6/14/87	Х	11
11 16	=	11	r	25-56	1,,,	. 81-39	520.8	=	11	=	*<	Ħ
" 2.7	=	=		25-56	39.485	81-39	45,593	= . •	11	=	ъ.	£
" 18	=	=		25-57	56.5	81-40	67.0	11	11	=	-54	=
" 20	=	- 11		25-57	3	07-T8	30.148	=	=	=	Х	=
n 21	=			25-57	95.7	81-40	4-5,802	=	Ξ	:	×	<u>=</u>
11 22	11			25-57	140.5	81-40	55.444	=	=	=	घ	=
17.74	==	1		25-57	121	51-41	13.697	Ξ	æ	=	প্ৰ	=

This form shall be prepared in accordance with Hydrographic Manual, Publication 20.2, Sec. 1-55, 2-39, 6-36, 7-18 to 22 inclusive, and Fig. 79. Positions of charted The data should be landmarks and nonfloating nide to navigation, if redetermined, shall be reported on this form. Revisions shall show both the old and new positions. considered for the charts of the area and not by individual field survey sheets. Information under each column heading should be given. * TABULATE SECONDS AND METERS

OSCOMMED 16234-PB1

COAST AND GE

C&GS FORM 567

U.S. DEPARTMENT OF COMMERCE TIC SURVEY



19 67

July 5

Maples, Fla.

NONFLOATING AIDS OR FAINDMARKS FOR CHARTS

TO BE CHARTED XTOME OUT TWO TOME DELETED STRIKE OUT TWO

I recommend that the following objects which have (harening) been inspected from seaward to determine their value as landmarks be charted on (deleted from) the charts indicated.

The positions given have been checked after listing by __

			,			ļ	F 1/3	William H,	Shearonse	E	itef of	Chief of Party.
				D.	POSITION			METHOD		TRAH	THAND	
STATE	FLORIDA		LAT	LATITUDE*	LONG	LONGITUDE 4		LOCATION	#100 #00 #00 #00 #00	10 M C		CHARTS AFFECTED
CHARTING	DESCRIPTION	BIGNAL	•	D. M. METERS	-	D. P. MEYERS	БАТОМ	CONVEY No.		KSNI	1410	
	BIG MAKCO RIVER							2962T-T	10t 6/14/61	M		1254
Daybn 25	. }		25-57	17.560	31-41	32.095 892.9.	M.A. 1927		-	×		=
11 27			25-57	36.401 1120.2	81-42	27.318	=	==	=	M	_	=
n 28			25-57	40.580 748.8	31-42	57.467 1042.3	t t	7-12986	6/20/67	≱ ₫		=
									,			
		,										Ì
							-					
		47								-	-	
										_		
											_	
						i i					_	
			<u> </u>									
											•	

This, form shall be prepared in accordance with Hydrographic Manual, Publication 20.2, Sec. 1-55, 2-39, 6-36, 7-18 to 22 inclusive, and Fig. 79. Positions of charted landmarks and nonfloating alds to navigation, if redetermined, shall be reported on this form. Revisions shall show both the old and new positions. considered for the charts of the area and not by individual field survey sheets. Information under each column heading should be given. * TABULATE SECONDS AND METERS

USCOMM-DC 16234-P81

Positions of charted

U.S. DEPARTMENT OF COMMERCE ETIC SURVEY COAST AND G



19-67

E

Everglades City,

MONHECOATING AIDS OR LANDMARKS FOR CHARTS

C&GS FO \$567

STRIKE OUT TWO TO BE CHARTED TO BE CHEWISED TO BE CHEWISED TO BE CHEVELETED TO BE CHERTED TO BE CHEMINED TO SERVICE THE CHEMINED THE CHE

I recommend that the following objects which have (hate hate has been inspected from scaward to determine their value as landmarks be

The positions given have been checked after listing by charted on Adelited from) the charts indicated.

Chief of Party. William H.

CHARTS AFFECTED 1254 1254 1254 1254 1254 1254 125 TRAHO BROKENTO TRAHO SKOHZKI TRAND ROSSAN Sherranse 8/8/67 6/22/67 6/17/67 6/22/67 5/23/67 7/6/57 77/6/197 LOCATION T-12986 12938 Priang. I-12936 Photo METHOD OF OCATION AND BURVEY No. 129551-1.2986 hoto Pl -12788 -12989 Williem II DATUM 1927 Ξ = = :: =: 11.452 318,3 25,70 1.67.2 43,316 1205.6 481.4. 11,23 312.0 319.6 D. P. METERS 7.800 164 LONGITUDE This position coind Gram W.P. Scaled nosition 46 POSITION 83 ۰ 81 a {c) 60 26.879 05.9 181,6 31,27 338.6 608.4 52.870 D. M. RETERS 30.941 55.430 LATTTUDE 00 Ω Ω V. 71 덗 5 50 q 55 3 (V) 8 u CV BIGNAL ASVERGALDES, MUNICIPAL W.T., 194 atop white white Crange & White structure ැප් زخ light skeleton steel, orange ht= 140(145) orange avnithit in field. atop apartment house ht= 97(102) DESCRIPTION Ç steel NIEV.TED, silver ht=144(143) skeleton steel, ht=531(534) Skeleton steel, ht= 200 (271) Rotating W & wood, skeleton ht= 72(77) (39)69 skeleton FLORIDA G.P. not 51 HICKOLAVE TOLES MICHCHAVE OBS. TOMER FETTROUSE CHARTING TV TO ER BEACON TOARR BTATE AERO TANK TANK

٠<u>.</u> Ų.

OSCOMMED 18234-PET D The data should be This form shall be prepared in accordance with Hydrographic Manual, Publication 20.2, Sec. 1-55, 2-39, 6-36, 7-18 to 22 inclusive, and Fig. 79. landmarks and nonticating aids to navigation, if redetermined, shall be reported on this form. Revisions shall show both the old and new positions. considered for the charts of the area and not by individual field survey sheers. Information under each column heading should be given.

* TABULATE SECONDS AND METERS

NAUTICAL CHART DIVISION

RECORD OF APPLICATION TO CHARTS

FILE WITH DESCRIPTIVE REPORT OF SURVEY NO. _T-12988

INSTRUCTIONS

A basic hydrographic or topographic survey supersedes all information of like nature on the uncorrected chart.

1. Letter all information.

2. In "Remarks" column cross out words that do not apply.

3. Give reasons for deviations, if any, from recommendations made under "Comparison with Charts" in the Review.

CHART	DATE	CARTOGRAPHER	REMARKS
1254	9-30-68	m H Wall	Part After Verification Review Inspection Signed Via
· — · -			Drawing No.
			Full Part Before After Verification Review Inspection Signed Via
· · · · · · · · · · · · · · · · · · ·			Drawing No.
			Full Part Before After Verification Review Inspection Signed Via
			Drawing No.
			Full Part Before After Verification Review Inspection Signed Via
			Drawing No.
			Full Part Before After Verification Review Inspection Signed Via
			Drawing No.
	<u> </u>	<u> </u>	
			Full Part Before After Verification Review Inspection Signed Via
			Drawing No.
	<u> </u>	<u> </u>	
	<u> </u>	<u> </u>	Full Part Before After Verification Review Inspection Signed Via
			Drawing No.
.			
		<u> </u>	Full Part Before After Verification Review Inspection Signed Via Drawing No.
	j		Drawing No.
	<u> </u>		Full Part Before After Verification Review Inspection Signed Via
			Drawing No.
	 - 		
			Full Part Before After Verification Review Inspection Signed Via
			Drawing No.
	 - 		
 -			
	i —		
··			
			· ·
	j i i		