DESCRIPTIVE REPORT. Topo. Sheet No. (3) 40.73 Locality: Whishis Boy. Chisnik Lascon Alaska Pen. Chignik Bay —			
DESCRIPTIVE REPORT. Topo. Sheet No. (3) 4073 LOCALITY: Chignik Bay. Chimik Lagoon Alaska Pen. Chignik Bay		DEPARTMENT OF COMMERCE	
Topo. Sheet No. (3) 4073 LOCALITY: Chignik Boy, Chignik Lagoon Alaska Pen. Chignik Bay —		State: S.W. Alaska	
Chignik Bay —	(C) 3	DESCRIPTIVE REPORT.	
Chignik Bay —		Topo. Sheet No. (3) 4073	_ _
Alaska Pen. Chignik Bay —		LOCALITY:	
Chignik Bay —		Chignik Boy, Chiznik Lagoon	
		Alaska Pen.	<u>`</u>
A L Pauls Cli III aakaa		Chignik Bay —	
Anchorage Day to Chignik Lagoon		Anchorage Bay to Chignik Lagdon	
1924		1924	
CHIEF OF PARTY:		CHIEF OF PARTY:	
Clem 1. Garner		Clem 1. Garner	_
			· -
	1		<u></u> .
			

DESCRIPTIVE REPORT

to

accompany Topographic Sheet #3 Chignik Bay, S. W. Alaska.

The work on this sheet was done under instructions to the Commanding Officer, U. S. S. DISCOVERER, dated March 11. 1924

<u>LIMITS</u>

Shore line joins topographic sheet #2 on a line extending from triangulation station Chignik to Triangulation station Summit, thence to Triangulation station Snowy Mt., thence for two miles south west along ridge lines. On the north and west connection is made with topographic sheet #4 at hydrographic station Fir, a pile of dright with a white cloth banner.

CONTROL

Control for the work on this sheet consists of 23 trian - gulation stations. Triangulation station Rock off Eagle Rock was found to be in error. The proper position was determined to be about 110 meters East of its given position and this position was later verified by new triangulation. Triangulation Station Red Mountain could not be identified with certainty. Triangulation station Mud was not recovered, but a large yellow clay bank was found in its position. Likewise Triangulation station Yellow Pole was assumed to be a fallen flag pole, the base of which checked the location of the station.

METHODS

The work was begun at Triangulation station House, orienting on Triangulation station Nigger both of which had been plotted temporarily one minute to the south of their true position. After the location of the shore line had been extended a sufficient distance to the south, position of stations and shore line was shifted to the proper place. The topography in Chignik Lagoon was done in advance of triangulation of 1924 and after these stations were plotted an error in distance of about $\frac{1}{2}$ of 1% was adjusted. The shoreline from Triangulation Chignik to Eagle Rock consisting in the main of Anchorage Bay was transferred from Photostat Copy of Sheet No.2802 which copy is attached to this sheet. The work of revision on the copy was done by Lieut. M.O. Witherbee. Corrections in red ink indicate new structures; corrections in blue indicate features which no longer exist.

GENERAL DESCRIPTION OF COAST

The head land east of Anchorage Bay is a smooth perpendicular rock cliff, 295 feet high, with a narrow rocky bench at its foot. The point west of Anchorage Bay is easily identified by Eagle Rock, a small rocky island 120 meters x 80 meters and 100 feet high, with a small rock 30 feet high and 90 meters to the northeast of it. Niggerhead is a smooth

perpendicular, black cliff, 425 feet high with a narrow rocky beach at its foot. Kelp makes out 150 meters around this head land. The sand spit across the mouth of the Lagoom is low, grass covered and at its northern end are found several small sloughs and swamps. Except for the channels in the Lagoon the entire bottom is covered with eel grass and dries at low water. A large part of Mud Bayalso dries at low water. Chignik River, a very crooked, shallow stream flowing into the southwest corner of the Lagoon drains Black Lake and Chignik Lake. The latter lake lies about 4 miles west of Mensis Point. Boats drawing two or three feet of water can enter Chignik Lake on spring tides. The terrain is covered with a thick growth of grass and alder bushes to an elevation of one thousand feet. Snow patches above this line exist throughout the summer months. A small glacier is found 3 miles south of the head of Mud Bay. Mountain summits are often obscured by clouds and promient shoulders are easily mistaken for the true summits. The trail from the Lagoon to Kuiukta bay (locally known as Dornei Bay) is overgrown with grass and difficult to follow. The divide is low, however, and small skiffs are dragged across it in the winter. .

Three small islets are found 700 meters south of Chignik Island. Their height is about 20 feet.

NAMES

. Doris Bay, as shown on Reconnaissance Sketch by Officers of U. S. F. C. S. ALBATROSS in August 1897, is locally known as Mud Bay. The eastern arm of Chignik Lagoon is Mallard Duck Bay: the island is shown as Chignik Island on private land survey sheets. The following points were given the local names by which they are known. Brown's Pt., Rocky Pt., Green Pt., Mensis Pt., and Hume's Pt., all of which are in Chignik Lagoon. Nigger Head is also a well established local mame!

LANDING FIELD

See Letter 417 of 1930, HB, The spit at north end of Chignik Lagoon is recommended as an emergency landing field for aeroplanes. The ground is covered with a thick growth of grass and moss; producing a resilient turf. Several low and regular ridges extend the entire length of the spit but these would not interfere materially with air craft landing in the direction of the longitudinal axis. This spit offers the only possible site for such a field in this vicinity and could be improved without much expense.

Respectfully submitted,

Hubert A. Paton, Aid. Topographer.

Huliert a. Paton

Approved and forwarded.

CLEM L. GARNER, H. & G. E. Chief of Party.

PLANE TABLE POSITIONS

9	Ob jec	t	Lat.	D. M.:	Long . :	D. M.	Remarks
			:	meters:	:	meters	
Top	o.Sta.	Fir	56 ⁰ 22 1	307:	158° 30':	308	: Pile of driftwood
				:	:		with white banner
79	17	Cab :	21':	880:	30 1:	460	Largest cabin of
ñ	ř	Church	21':	547 :	31 • :	20	Indian village Church in Indian
٠,		Offer Off		O#1 :	21.1	20	village
īŧ	it	Mast	17':	1690 :	37 1 :	154	Flag pole APA
				-		- (Fishing Camp
- 11	11	Staff	17':	1054 :	371:	168	Mast of barge grounded
~	_	٠ ;	:	:	:		on beach above HWL
11	Ħ	.Yel :	17':	880 :	37 :	645	Front of Yellow house
-	-	. ;			:	:	· ·
. 11	Ħ	Ho :	: 16':	1833	38 1 :	655	Deserted house on
11	'n		:	:	== :		: Mensis Pt.
	. "	And :	161:	1514 :	33 1 :	938	West gable Anderson's
 11	. îi	Dwo I	*	438 :		077	house on Green Pt.
. "	· ••	Brel	201:	458 :	281:	937	Umbrella shaped rock
n	11 sr	Leg	201	200 :	291	657	10 feet high Shear leg behind camp
	,	105 a	. NO :	200 ;	45.	007	on Brown's Pt.
ñ	11	Col	201	532 :	28':	700	Small shack 240 meters
_	_			•		, , , ,	SW of CRP camp
Ħ	n	Riv :	201:	720 :	291	530	Yellow flag pole on
			:	:		:	CRP camp
11	11	Net	201:	1070 :	28':	194 :	Pole with triangle
	-			1	· •	:	•
11	11	Skul :	18':	1683 :	31 ' :	602 :	Flag pole Chignik
	ñ		:	:	 :.	170	Lagoon school house
सर	17	Pole :	17':	590 :	361:	138 :	Flag pole on island
	- tt	Shack :	201:	1200 :	29' :	649 :	Dosowtod I was abad
**		ourck :	ω·:	1200 :	49' \$	047 :	Deserted 1 room shed
Î	- H	Pinna cle	16':	1185 :	381:	975	Pinnacle rock about
		T TIMES C TO		**************************************			100 ft. high
ñ	11	Bum :	19	918	25':	977	Deserted house
					,	•	

A supplemental sheet showing continuation of contours beyond the southern limits of the sheet is also submitted.

AND REFER TO NO. 4-DRM

DEPARTMENT OF COMMERCE

U. S. COAST AND GEODETIC SURVEY

WASHINGTON January 23, 1926.

SECTION OF FIELD RECORDS

Report on Topographic Sheets Nos. 4073ª andb.

Chignik Bay, Alaska Peninsula

Surveyed in 1924

Instructions dated March 11, 1924.

Chief of Party, C. L. Garner.

Surveyed and inked by H. A. Paton.

- 1. The records as well as the plan and character of development conform to the requirements of the General Instructions, except that there are only one-third of the prescribed number of determined elevations.
- 2. The plan and extent of development satisfy the specific instructions.
- 3. The usual field drafting was done by the field party.
- 4. The junctions with the adjoining sheets are satisfactory and no further surveying is needed.
- 5. The descriptive report states that the spit at the mouth of Chignik Lagoon could be used as a landing place for airplanes.
- 6. The character and scope of the surveying and field drafting are excellent.
- 7. Reviewed by E. P. Ellis, January, 1926.

DEPARTMENT OF COMMERCE

U. S. COAST AND GEODETIC SURVEY

TOPOGRAPHIC TITLE SHEET

The finished Topographic Sheet is to be accompanied by the following title sheet, filled in as completely as possible, when the sheet is forwarded to the Office.

U. S. Coast and Geodetic Survey.

	Register No. (3) 4073 b
	State
	Alaska Peninsula General locality Ohignik Bay
	Locality
	Chief of party
	Surveyed by Hubert A. Paton
	Date of survey July 1924
	Scale
	Heights in feet above Mean High Water
	Contour interval .100 feet.
? ,	Inked by Hubert A. Paton Lettered by . H. A. Paton
-	Records accompanying sheet (check those forwarded): Photographs,
	Supplemental Sheet Descriptive report, Horizontal angle books, ####################################
	Data from other sources affecting sheet Photostat .Copy Sheet #2802
	W. Carlotte

Remarks: Bromide of original topographic sheet No. 2802 attached hereto shows 1924 topography in red. This comprises work showing new fish cammeries and changes in old ones. Revision of the entire topography of this bay was not found necessary and that part of the shore line which was not resurveyed is shown on the 1924 sheet No. 3 by dotted lines. The transfer from bromide No. 2802 to the 1924 sheet was carefully made by orientation on Chignik Light on the spit and Rock off Eagle Rock, both of which are determined by triangulation .