# 5917

12417

Form 504

U. S. COAST AND GEODETIC SURVEY

. DEPARTMENT OF COMMERCE

## DESCRIPTIVE REPORT

Type of Survey Planimetric Map

Field No. Office No. T-5917

LOCALITY

State Florida

General locality East Coast

Locality St. Lucie River - Stuart

Photos taken: Jan. 9, 1940

194 2

CHIEF OF PARTY

Lieut. Comdr. Kenneth G. Crosby

LIBRARY & ARCHIVES

DATE May 27-1947

B-1870-1 (1)

5917

Applied to chart 1289 8/17/43 G.T.E. (before review)
Applied to chart 1112 2/10,44 S.R. (before review)
Applied to chart 1247 3/18/44 G.T.E. (after review)

## TOPOGRAPHIC TITLE SHEET

The Topographic Sheet should be accompanied by this form, filled in as completely as possible, when the sheet is forwarded to the Office\_SHEET

FYEYS No. T-5917

#### REGISTER NO.

State Florida
General Locality East Coast
Locality St. Lucie River at Stuart
Date of Photo Scalel; 10,000 Decemposes January 9 , 19 40
Party: PASSET Air Photographic Party No. 1
Chief of party Lieut. Comdr. Kenneth G. Crosby
Field Inspected by : Lieut. J. D. Thurmond
Inked by Cornelius A. J. Pauw, Sr. Engineering Aid
Heights in feet above to ground to tops of trees
Contour, Approximate contour, Form line interval feet
Instructions dated April 3, 1940
Remarks:
966922

## SHEET NO. T-5917

## SUPPLEMENTARY SURVEYS

·	Name	Date	Hours
Control Surveys	JEH-WHS-JHSI	3: March & Spril	: 9½
Planetable Surveys		<u> </u>	
		Total	
FIELD INSPECTION			
Duran and San and Dhaha amanla	Ori Du D	- Nor-	: 7
Preparation of Photographs:		: Nov.	-
Field Work	JUI-PHE- GEV	: Jan.	: 114
Inking Notes			
Coast Pilot Notes	Tal 172	. Mars	. 14
Geographic Name Reports	rne	: May	: 14
Land Marks for Charts			
Description Cards	JDT- FHE-GEV	Feb. & March	54
Recovery Notes		Total	<u>•</u>
MAIN RADIAL PLOT		1000	189
MAIN IMPIAN IIOI			
Scale Plot	11211	* March	: 1
Projection on Base Sheet	orn Walan o <i>re</i> saa	March	: *
Projection on Survey Sheet;	wasn. Ullice	<b>\$</b>	:
Control Plotted	KGC	: April	: 13:3/4
Control Checked	WHS	: April	: 1½
Control Trans. to Base Sheet:	KGC	: April	: 1 : 2 : 4
Transfer Checked	VIHS	: April	: 4
Control Picked on Photograph:	HGB-JEH	: Feb.	: 11
Control Checked on Photograph:	CAJP	: March	<b>:</b> 7
Hydro & Topo. Stations Picked:	HGB-JEH- CAJP	: Feb. & June	: 16
Radial Points Picked	jeh	: March	: 11
Adjacent Centers Picked:		: Feb.	: 25\frac{1}{4}
Templates	HVR	: Apr.	: 31
Radial Plot		: Apr.	: 5
Radial Points Transferred:	JHSB-MMS-JEH	: Apr.	: 4 × 700
Transfer Checked		: Apr.	: 3 <sup>1</sup> ⁄ <sub>4</sub>
H & T Stations Scaled & Checked:		: June & July	: 10
AND TAX TOTAL Radial Points	CAJP	: June	: 14
Investigating		Total	1422
DETAILING			
Rough Draft	CAJP	May & June	: 185
Smooth Draft		·may -or ounc	10)
Difficont Plate.	······································	Total	185
COMPILATION			, ,
<u>.</u>			
Name overlay:		: June	: 15
Rescriptive Report:	CAJP	: July	: 7
Field Review	JAG	: July	: 18
		Total	40 .
Total time spent on Sheet		5	66 hours

#### DESCRIPTIVE REPORT TO ACCOMPANY SHEET NO.T-5917

#### GENERAL

This sheet was compiled from nine-lens photographs taken by the U. S. Coast & Geodetic Survey camera on January 9, 1940. The rough draft was made in accordance with the "Instructions for Drafting Air Photographic Surveys, Project H.T.242, dated April 3, 1940."

The general locality of the area covered is the Florida East Coast, St. Lucie River Inlet at the city of Stuart.

With the exception of the towns of Stuart and Palm City, the entire area is covered by lakes, ponds, marshes, and floodlands. The vegetation is comprised of grass, palmetto, palm, pine, and in the swamp areas gum and bay trees. Fringes of mangrove are common along the shores and extensive mangrove swamps occur at the entrance of the St. Lucie Canal and the mouth of Bessey Creek, been added in red and Some in Grack.

These

All buildings visible on the photographs have been shown with the exception of the center portion of Stuart town.

All roads and streets shown by double lines should be 0.6 m.m wide, with the exception of streets shown wider, in which case their actual width appears on this map drawing. All roads shown by a center-line only, should be shown 0.6 m.m. wide on the smooth draft.

#### CONTROL

The following ten (10) triangulation stations appear within the tracing limits of this sheet.

Reference	Station	STUART	(Tank)	1930	U.S.C.&	G.S.
Ħ		BUSH		1930	711	
t)		SPIT		1930	ii,	
- <b>&amp;</b>		CANAL		1930-194	42 "	
it		PALM		1930	11	•
Ħ		PHONE		1930	11	
11		MENDEL		1930	13	
ti		PISGAH		1883	11	
11		KRUEGE	ર	1930	. 11	
· 11		MAN		1930	11	
, II		PINEY		1930	11	

Triangulation Station Swan 1930, appears on this sheet, but falls outside of the detailing limits.

#### MAIN RADIAL PLOT

A continuous radial plot was run on April 22 - 24, 1942 inclusive, for the purpose of locating all photograph centers, all hydrographic stations, topographic stations, bench marks, azimuth marks, and radial points. The plot extended over the area covered by sheets T-5912 to T-5919, inclusive. All photographs in the area were used. It extends along the St. Lucie Canal from Stuart, Florida, south and westward to Lake Okeechobee at Port Mayaca. Photographs 4591, 4583 and 4584 are the northeast limits and photograph 4564 forms the westerly limits.

The plot consisted of 37 templates all being for 9-lens photographs and being controlled by triangulation stations as follows: 1 by 0: 12 by 1-2; 9 by 3; 8 by 4-8; 7 by 9-13. These templates were made in accordance with "Notes on Radial Plotting of nine-lens Photographs," dated April 9, 1940.

The control afforded by first and second order triangulation was sufficient on sheets T-5919, T-5918, T-5917 and T-5912. Triangulation control was very meagre on sheets T-5913, T-5914, T-5915 and T-5916, but it was felt that additional field observations were not necessary.

The usual practice of laying the plot was followed. This consisted of plotting the control on the survey sheets and then transferring it to the base grid sheets by matching grid squares. The agreement between the grid lines on the survey sheet and those on the base grid was excellent and no adjustment was necessary. After laying the plot, the intersections of the radial lines were transferred to the survey sheet by again matching grid squares as previously described.

The plot was laid only once with the exception of those templates on sheets T-5914 and T-5915. The laying of the plot began with the templates on sheets T-5917, T-5918 and T-5919 and proceeded southwest to triangulation station "Allen" on sheet T-5916. These templates were rigidly controlled. From that point to sheet T-5912 the templates were laid by holding intersections of radial lines and azimuth, and due to lack of control the templates on sheets T-5914 and T-5915 had to be laid three times before a satisfactory tie-in of control on sheet T-5912.

The agreement along the flight line and the intersections of radial lines to adjacent photographs was excellent, with exceptions as noted in this paragraph. About 98 per cent of the points established by the plot resulted from the intersection at a common point, of three to six radial lines. The remaining 2 per cent are instances where only two "cuts" could be obtained. These are mostly out on the wings of the photographs and while the value of the intersection will be determined by the draftsman, it is believed that the majority of them will be outside the detailing limits. In six or eight instances the point was selected at the center of gravity where the radial lines did not form a common intersection. In no case were the sides of the triangle of error greater than 0.25m.m. away from the point selected.

The conditions in the preceeding paragraph apply to seven of the eight sheets of this plot. The other sheet (T-5814) was the "weakest" of the plot, insofar as control is concerned, and a common intersection of radial lines was not obtained in some instances on the northern half of the sheet. There are fourteen of these instances and in each case the "cuts" were transferred to the survey sheet for further investigation by the draftsman.

The points on the southern part of the sheet were picked at common intersections and after the draftsman has made further investigation, it is believed the detailing will be accomplished with the desired accuracy.

To summarize - the plot is considered "strong"; no large or unusual adjustments were necessary; and that all points are picked with 0.25 m.m. of their true position.

Various colored inks were used on the photographs and survey sheets to designate triangulation stations, topographic and hydrographic stations, and radial points.

. The following key is furnished for future reference.

#### Photographs

Triangulation and traverse stations......2.5 mm blue circle Hydrographic and topographic stations.....2.5 mm green circle Radial points in main plot .........2.5 mm red circle

#### Survey Sheet

#### NON-FLOATING AIDS

Non-floating aids to navigation appearing on this sheet have been listed on Form 567, which has been made apart of this report. Seven aids were located from sextant fixes and five from radial plot, two of which were checked with sextant fixes. Kennings Lighthouse used in sextant fixes is a cafe building similar in shape to a lighthouse.

#### INTERPRETATION OF PHOTOGRAPHS

The photographs were clear and no unusual difficulties in interpretation were encountered.

#### FIELD INSPECTION

Field inspection was made by Lieut. James D. Thurmond by truck and skiff during the months of January and February, 1942. The field notes were adequate throughout the area covered by this sheet. The legend used by the field inspector has been made part of this report.

#### BRIDGES

Type and kind of structures have been indicated and horizontal and vertical clearances noted.

#### DETAILING

The celluloid was treated with dry magnesium carbonate prior to inking throughout the drawing.

The scale of the photographs was good, without exception. With the exception of the westernmost portion of the sheet there were ample overlaps, (approximately 70%). This western portion consists of undeveloped glade lands and is of relatively slight importance.

No additional radial points were intersected as there was ample control. However, the compiler did re-intersect 24 doubtful points and made slight corrections wherever such was found to be desirable. Practically all points gave a common intersection from four or more cuts.

The stereoscope was employed to determine the exact positions and shapes of tall buildings and other complicated features such as marine railways, wharves, docks, bridges, etc.

Symbols and labels have been used freely wherever time could be saved without reducing the correctness of interpretation of the map. The legend of symbols is identical with the one used by the field inspector, which is apart of this report.

The entire sheet was detailed in accordance with current instructions for this project.

#### JUNCTIONS

This map drawing joins Sheet No. T-5918 on the north, Sheet No. T-5919 on the east, and Sheet No. T-5916 on the south. All junctions are in agreement.

#### GEOGRAPHIC NAMES

A special report on the investigation of Geographic Names for the St. Lucie River, Cross State Waterway and Lake Okeechobee was made and submitted by Harold A. Duffy, Sr. Photogrammetric Aid. All geographic names are as shown on the name sheet.

#### LAND MARKS

No prominent land marks appear on this sheet.

Respectfully submitted

Sr. Engineering Aid

Cornelius A. J

Forwarded:

Chief of Part

## LEGEND USED FOR FIELD INSPECTION AND DRAFTING PROJECT 242 - 1942

#### TREES **PONDS** ~ Pine Pi - Pond Су - Cypress Cy P - Cypress Pond Palo - Palmetto - Intermittent Pond Palm-- Palm D T - Deciduous trees (broad leaf) SHORELINE Cit - Citrus (orchard) Mix - Pine, cypress & Dec. trees H.W.L.- mean high waterline (solid (Density) red line - fast land) Sct. - Scattered L.W.L.- low waterline (dashed red line) t.w. - Thinly wooded L.L. - Light line (solid blue line for h.w. - Heavily wooded mean high water line on marsh) Scr. - Scrub trees; Dk - Dock Pr- Pier VEGETATION Se W - Seawall Bkhd - Bulkhead - Cultivation Conc - Concrete Gr - Grass Wo - Wooden T Gr - Tall Tropical Grass Jet - Jetty - Marsh (dashed blue line on - Dolphin Dol inshore limits) Pile - Pile (give type) - Marsh grass in water (dashed blue s - Sand line on offshore limits) Mud - Mud Sw - Swamp Rk- Rock or Rocky Mg - Mangrove Sty - Stony Hdg - Hedge W - Water Blf - Bluff (height) STREAMS BUILD INGS Ca - Canal (width) Cr - Creek - House, barn or building - Ditch (width) - Ghurch (give name) Gh I S - Intermittent Stream Ct H - Court House (give name) PDU - Probable drainage unsurveyed Bo H - Boat House Brg - Bridge or symbol P.O. - Post Office (give name) - Culvert Cv R.R.Sta-Railroad station (give name) Lev - Levee - Hospital (give name) Hos Sch - School (give name) F.G.S.- Florida Geodetic Survey U. S. E.- U. S. Engineers MISCELLANEOUS USBS - U.S. Biological Survey ROADS & RAILROADS FΒ - Fire Break (maintained) FBX - Fire Break (abandoned) Rd 1 - 1st class road (paved) Cem - Cemetery Rd 2 - 2nd class road Park - Park (give name) - Trail Tr F.T. - Fire tower - Railroad RR T.T. - Transmission tower(tall steel) - Overpass( state the kind) 0 P P.L. - Power Line - Underpass(state the kind) Shoal - Approx. limits by long dashed - Abandoned trail, road, etc. line for use by hydrographer.

R H ab- P.R. abandoned (grade only)

Remarks

Decisions

	Remarks.	Decisions
1		272801902
2		North Fork
3		" North Fork 271801902 South Fork
4		п
5		11
. 6		1)
7		11
8	,	11
9		n
10		11
11_		tt .
_12		272801-02
13		n
14		11
15		n
_16		tt .
17		tr
18_		tt
19		U U
_20		te
21_		11
22_		Railway Guide
23		1941 Off. State Road Map
24	No. 85 on most maps	u
25	No. 140 on 1939 Fla. Transp. Map.	11
26		n ·
27 M 234		272801-03
M 234		1

GEOGRAPHIC NAMES  Survey No. 17-5917			or or or	D Popular	\$ .o	Maga	G. G. G.	Wood WENDING	15 John	*
Name on Survey		Chor. Of	40. O.	2 Mag	E E	On local Mada	G. Gay	gord Mc	25. K	
	Α,	В,	<u> C,</u>	/ D	-	<del>-</del>	<u> </u>			
St. Lucie River										1
√St. Lucie River North-Fork	. v	_								2
/St. Lucie River South-Fork	<u>.                                     </u>						_		<u> </u>	3
Frazier Creek						<u> </u>				4
Mulliham Cove					ļ	<u> </u>				5
Bessey Point						ļ				6
Poppolton Creek										7
Danforth Creek										8
Palm City										9
/- Stuart										10
/										11
Kreuger Creek ' / Pisgah Hill										12
1		_								
Warner Creek ·						<del> </del>				13
Rio St. Lucie Terrace.										14
Rio St. Lucie										15
Haney Creek										16
Britt Point		<u> </u>								17
Dyer Point						<u></u>		· .		18
Bessey Creek		_								19
Coconut Point							_			20
Mile Lake		_					<u> </u>			21
Florida East Coast Ry				· 					<u> </u>	22
U.S. Highway No. 1									l	23
Florida Highway No. 109										24
	✓					in the state of th	in J h	اعتبد في ا	1	25
Florida Highway No. 111				•	\\ s.!	L H	c\( (			26
Van Seggern Creek		wth	T 56	(8)	•				į	27
2 - VEOGE A CARE	, ,			13/						M 234

 $\nu$ 

5917	
	5*
4593 4594 12:03 P. M. 0.8 0.8	galender Salender
4595 4596 п. п. 12:06 Р. М. 0.7	
4580 4581 4587 4 11.0 4587	
4588 " " " 11:56 A.M. "0.9	
St. Lucie Inlet (jetty), Florida Reference Station: Mayport, Florida	
1:10,000 ÷ .9908 1:10,000	
27.0	and the second s
19.5	
Stuart (Tank) 1430, r/934(d) 12:00: 27° 11' 45":041(1386.31) 1927 N. A.	m.)
	n).
F/a. Fost Zone x= 743,468:15	n Almej na leten na leten na leten al ¥an
y= 1,091,046.08	**

## United to 15 5 for 1280 1 increased distribution of 242 - 1942

Special page	
And the second s	N.A.
Pi - Pine	
Cy - Cypress	P - Fond
Frio - Palmetto	Cy P - Cyprose Pond
Palm- Palm	I P - Interestrent Pani
Of - Decideous tres (troad leaf)	24093.D&
lit - litrus (archard)	
His - Pine, cypress & Joc. trops	Mereles meet high neteriles (sol d
(b maity)	red line - fuck hand)
pet Sectioned	Lettele- lo setterline (casted res line)
tows - Thirdy wooded	Lois - Light line (solid blue 1 - a for
here - heavily was sed	man ligh water line on to reh)
or serub tres;	Dk - Deck
	Pr - Pier
Yan Tarihi	Se n - Seamall
· •	Mond - Pullchend
C - inlaivables	Gune - Comprete
II - Ina	- HO - Rooden
Gr - 11 replact trace	Jat - jetty
- harsh (a shed blee line on	Dol - Dolphin
inspere limits)	File - Pile ( ive type)
a servi , rese in ester (dushed blu	
l'he on offshore limits) le - l'enus	Itali - Bad
ag — organiya ag — organiya	ilk - lock or Hooley
- Bedge	Sty - Stary
enge pro temperatiyan	er and the second of the second of
	Mr - Murs (noteta)
	Gure Maint markers
Ch = Janel (H.Jeb)	1634-1843
Cr - Creek	R - white, him or building
D itom (right)	th - Merch (give need)
IS - intermittent Stream	of " - burt flows (sive name)
#NU - Probable drainage unsurveyed	# H - Wet House
Arg - Oridge or symbol	".U 'Ost O: ries (dive mess)
or - outrest	industrialized station (Are mas)
Let - Lette	iles - ilegrátel (ive muse)
Barra Shambar da asa Kauma .	Och - Ochool (give mane)
F.G.S Florida Journal Survey	and the second s
De te de- de Se incineero 1966 - Debe siglopical Survey	The state of the s
AND A ONE STREET, TOST SESARE	<b>a</b> h sa
904.45 4 Tt. 61.68	F - Fance
illeri k Illeria	PB - Fire Break (minteined)
id 1 - lat class road (paved)	ill - Fire Break (abandoned)
#4 2 - 2nd class road	John - Countary
	Park - Park (give name)
RR - direct	ToT Tire tower ToT Tunemission tower(tall steel)
OP - Overpass( at te the kind)	Pole a function constant stati
Uf - Laderpass(state the kind)	thoul - Approx, limits by long daubed
- Alemioned trail, read, etc.	line for use by ludre replantar.
a # sb- Pois abundaned (grade enly)	Trade to any of identifications
<b>₩</b> n#n - · · · · · · · · · · · · · · · · · ·	•

#### Division of Photogrammetry

#### Review of Planimetric Map T-5917

This map was compiled in the Tampa Photogrammetric Office in 1942, but Washington Office processing was delayed because of war map work of the Bureau. The map was reviewed in 1943, printed in 1945, and registered in 1947.

#### Field Inspection and Detailing.

These were generally adequate. However, the following changes shown in red on the manuscript were necessary during review:

- (1) At Lat. 27°10'+, Long. 80°15'+ piling and dock ruins were added to 5917.
- (2) Change in mouth of creek at Lat. 27°13'+, Long. 80°13'+.
- (3) Also, additions were made in clearance data for Stuart bridges and cables.

#### U. S. Engineer Stations.

Geographic positions were determined from local grid positions for U.S.E.D. Stations Riv, Baker, and Bridge which previously had not been computed but which had been radially plotted. These were plotted as triangulation stations and in two cases fell exactly on the radial plot positions; the third point fell slightly off the radially plotted point but showed that the plot was very strong.

#### Bridge Clearances

The following is a list of clearances given by the field inspection party for bridges at Stuart and Palm City. These do not agree with the U.S.E. bridge book:

	Stuart, Fla.		
Туре	Vertical	H	orizontal
RR Bridge (Bascule)	6.6 ft. (H.W.)		50 ft.
Hwy Bridge	13.0 ft. (H.W.)		80 ft.
Overhead Cable	80 ft.		

## Palm City, Fla.

Type	Vertical	Horizontal
Hwy Bridge	6.2 ft. (H.W.)	60 ft.

#### Comparison with Previous Surveys.

T-1571	1:20,000	1883		
			Graphic con	trol'
T-4534b	1:10,000	1930 )	•	CLOT
T-4534a	1:20,000 `	1930 )	surveys	

There was no material taken from above topographic sheets and they can be considered as superseded by T-5917.

#### Comparison with Nautical Charts.

T-5917 has been applied to chart 1289 prior to this review. The changes mentioned in the preceding paragraphs as made during review are shown in red on the manuscript and are of consequence to the chart.

Reviewed under the direction of D. H. Benson in December 1943.

This report prepared by B. G. Jones from reviewer's notes in May 1947.

APPROVED BY:

Technica V Assistant to the Chief, Div of Photogrammetry Div. of Charts

Chief, Nautical Chart/Br.

Chief, Div. of Photogrammetry Chief, Div. of Coastal Surveys

## NAUTICAL CHARTS BRANCH

## SURVEY NO. 7-59/7

## Record of Application to Chart's

DATE	CHART	CARTOGRAPHER	REMARKS
6-19-47	1289	Modros	Bater After Verification and Review July
			Before After Verification and Review
			Before After Verification and Review
			Before After Verification and Review
• • • •			Before After Verification and Review
			Before After Verification and Review
			Before After Verification and Review
			Before After Verification and Review
			Before After Verification and Review
			Before After Verification and Review
			·

M-2168-1

A basic hydrographic or topographic survey supersedes all information of like nature on the uncorrected chart. Give reasons for deviations, if any, from recommendations made under "Comparison with Charts" in the Review.